

DISTRICT I  
Box 1980, Hobbs, NM 88240

DISTRICT II  
Drawer DD, Artesia, NM 88210

DISTRICT III  
Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30162
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-8600
7. Lease Name or Unit Agreement Name Tonto "23"
8. Well No. 1
9. Pool name or Wildcat North Airstrip Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: Oil <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>
Name of Operator J&G Enterprise Ltd., Co.
Address of Operator P.O. Box 100, Artesia, New Mexico 88210

Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line
Section <u>23</u> Township <u>18S</u> Range <u>34E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3974 GR</u>

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
FORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
ORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed  
rk) SEE RULE 1103.

1. Set CI bridge plug @ 8480'.
2. Perforate 7404 to 7416' (12').
3. Acidize w/1500 gals 15% NEFE & swab back.
4. Frac w/48,000# 20/40 sand.
5. Put well to pumping.

I certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Jackson TITLE President DATE 8-4-95  
PRINT NAME J. T. Jackson

TELEPHONE NO. 505-746-9680

Space for State Use)

Original Filed by  
Paul P. P. P.  
G. G. G.

FILED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_