State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSE	ERVATION	DIVISIO)N				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505			WELL	API NO.	30-025-3	30258	
	Sani	tare, NW 8/3	103	5. Indi	cate Type o	of Lease		
DISTRICT II 811 S. 1st Street, Artesia, NM 88210					ED 🗀	STATE [FEE >	\overline{a}
DISTRICT III						s Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410				İ				'
	CES AND REPORTS ON	N WELLS	<u>. </u>					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name			
(FORM C-101 FOR SUCH PROPOSALS.)					NORTH HOBBS (G/SA) UNIT			
1. Type of Well:								
Oil Well X 2. Name of Operator	Gas Well Othe	er		8. We	11 No.	212		
OXY PERMIAN LTD.								
3. Address of Operator				9. Poo	name or \	Vildcat	HOBBS (G/SA	۸)
1017 W. Stanolind Rd., HOBBS, N.	1 88240	505/397-8200						
4. Well Location								
Unit Letter <u>C</u> : <u>639</u>	Feet From The NORT	H Line and	1885	Feet From T	he	WEST	Line	
Section 32	Township 185	S	Range	38E	NMPM		LEA County	1
	10. Elevation (Show whether 3646 GL	DF, RKB, RT GR,	etc.)					
	ppropriate Box to Indica	ate Nature of N	otice, Repo	rt, or Other D	ata			
NOTICE OF INTEN	ITION TO:			SUBSEQUE	ENTRE	PORT OF:	•	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK						ALTERING (CASING	<u> </u>
TEMPORARILY ABANDON (CHANGE PLANS	COMME	NCE DRILLII	NG OPNS.		PLUG & AB	ANDONMENT	
PULL OR ALTER CASING		CASING	TEST AND	CEMENT JOB				
OTHER:		OTHER:	Open A	dditional pay	– San A	ındres		X
12. Describe Proposed or Completed Operations	Clearly state all pertinent det	ails, and give perti	nent dates, inc	clading estimated	date of sta	arting any prop	osed work)	
SEE RULE 1103.								
1. RUPU. Pull ESP production equipm	ient.							
2. Perforate the San Andres Zone from	4084-4131.							
3. Stimulate well with 2100 g NEFE H	CL Acid.			/		•	·	
4. Run Reda ESP euipment on 130 jts:	2-//8" tbg.			1.3	J ,	_		
5. Bottom of tbg @4014'.6. Install QCI wellhead connection.				//:	256	200	•	
7. RDPU. Clean Location.				1:-	$\hat{B}_{e}^{*}\rho$. [D		
				11	6-	_+7/5 ,		
				/5	• ,	$G_{\mathcal{O}_{i,j}}^{\mathcal{O}_{i,j}}$	• : /	
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		•	7	
						1	/	
I hereby certify that the information above is true	and complete to the hest of m	v knowledge and h						
7/14	100.+			ים דרכוו		DATE	12/07/2002	
SIGNATURE X JULY	active.	TITLE	SR. ENC	GR TECH	TELL	EPHONE NO.	505/397-8200	 6
TYPE OR PRINT NAME Robert Gilber	rt	OPICINIAL	````		TELL		303/39/-0200	
(This space for State Use)		ORIGINAL SIGNED BY GARY W. WINK OC. ELETHURGER				DEC 1 0 20 02		
APPROVED BY		OC FIELDIE	EP RESENT	ACIVE II/STA	SEE MAI	DAME NACER		
CONDITIONS OF APPROVAL IF ANY:				***************************************				