

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

E.
re.

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER Non-Producing TA		5. LEASE DESIGNATION AND SERIAL NO. NM-053380	
2. NAME OF OPERATOR Bison Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 5809 S. Western Suite 200, Amarillo, Texas 79110-3607		7. UNIT AGREEMENT NAME Caviness 10 Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2026' FSL 1961' FEL unit 9		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3996' DF		10. FIELD AND POOL, OR WILDCAT measured: Escalante AS GORDON ABO	
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10 T18S-R33E	
		12. COUNTY OR PARISH Lea	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☐
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Re-completion attempt

☐
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2-19-91 Set GIPB @ 8085'. Pressure up by Knox Services to 1100#. Lost 95# in 20 min.
2-20-91 Spot 30 sx cmt. on top of plug.
Perf. Abo w/2 JSPF 7342-52'. (21 Holes)
Set pkr. @7240'. Fluid level 500'.
2-21-91 Swab 60 load water w/show of gas and trace of oil
Pressure up back side to 700# and acidize w/2500 gal 15% HCl and 31 ball sealers.
Pressure 1100# to 600#. SITP-Vacuum.
Swab and recovered 68 Bbl. load water-no show.
2-22-91 SITP 0# F.L. 500'. Swab 52 BLW; no show
FL 1200'. SD to study

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President

DATE 2-28-91

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side