

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
		<p>5. State Oil & Gas Lease No. A 4096</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator OXY USA Inc.</p>		<p>8. Farm or Lease Name State EA</p>
<p>3. Address of Operator P. O. Box 50250, Midland, TX 79710</p>		<p>9. Well No. 1</p>
<p>4. Location of Well UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> NMPM.</p>		<p>10. Field and Pool, or Wildcat Reeves (Queen)</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3915.6 GR</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. of 4780' Lime & Dolomite. Plugged and abandoned. Drilled a 7 7/8" hole from 378' to T.D. of 4780' in Lime & Dolomite and after receiving verbal approval from Jerry Sexton w/NMCD in Hobbs, NM, this well was P & A'd in the following manner:

1. Set 26 sx. CL. C cement plug @ 4516'-4416' across Queen
2. Set 26 sx. CL. C cement plug @ 3200'-3100' across base of salt
3. Set 26 sx. CL. C cement plug @ 1900'-1800' across top of salt
4. Set 27 sx. CL. C cement plug @ 428'- 328' 1/2 in & 1/2 out of 8 5/8" csg. shoe
5. Set 10 sx. CL. C cement plug @ 30' to surface.

Set a 4" Dry Hole Marker 4' above ground to designate P & A location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. A. Votran</u>	TITLE <u>Dist. Oper. Mgr. - Prod.</u>	DATE <u>4-13-88</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 29 '88</u>
CONDITIONS OF APPROVAL, IF ANY:		