State of New Mexico Submit 3 Copies To Appropriate District Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-30480 District II **OIL CONSERVATION DIVISION** 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE X FEE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 B-2148 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) LEAMEX 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 8. Well No. Phillips Petroleum Company 055 3. Address of Operator 9. Pool name or Wildcat 4001 Penbrook Street Odessa, TX 79762 MALJAMAR GB/SA 4. Well Location 1980 ____feet from the ___ EAST Unit Letter 1980 line and feet from the SOUTH Township 17-S Range NMPM LEA County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4132.4' GR (UNPREPARED) 11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING **MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: ACIDIZE, SWAB, & DROP FROM REPORT

line

|X|

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

5/20/01---MI RU POOL DDU #587

| 5/21/01COOH W/ROD STG & PUMP. NIPPLE UP BOP SCRAPER & TRIP TBG TO 4630'. RU TBG TESTER, TE WATER. SISD. | P. COOH W/TBG EST TBG IN HO | i. TRIP SAI ILE SET PKI | ND PUMP TAG R @ 4262'. | FILL 4680'. I LOAD BACK SIDI | PU CASING E W/FRESH | |
|--|---|---------------------------------------|--|---|------------------------|-------------|
| 5/22/01MI RU HES, ACIDIZE GRAYBURG-SAN ANDR & 1100 LBS ROCK SALT IN GELLED BRINE. HAD GOOD PSI, ON 4TH PRESS @ 1790 PSI. MAX PRESS 1810 P VACUUM. TOTAL LOAD 252 BBLS. SI WELL. RD HES. SEATING NIPPLE, GETTING BACK 400-500' OF FLUID | D BLOCKING AC PSI, AVG PRES RU TO SWAB: | TION ON 3 S 1065 PS FLUID LE | -4 STAGES. I, AVG RATE VEL 3600' F | 3RD PRESS INCE 3.0 BPM . IS: FROM SURFACE, S FR. SISD. | REASED TO : | 1290 ON |
| I hereby certify that the information above is true and complete to the | | _ | | | | |
| SIGNATURE CULLS to the Sun for Soms | TITLE SUPV | . REGULATI | <u>[ON/PRORATI</u> | ONDATE_ | 6/7/01 | |
| Type or print name L.M. SANDERS | | | | Telephone No. | 915/368-1 | 1488_ |
| (This space for State use) | | | _{γ',Ω} Βγ | | | 1, 200 |
| APPROVED BY | _ TITLE | · · · · · · · · · · · · · · · · · · · | | DATE | | |
| <u>C</u> | | | | | | |
| | | | | | | |

LEAMEX #055 CONTINUED

5/23/01-- SWAB RPT: TBG PRESS 150 PSI. FLUID LEVEL @ 4000' FROM SURFACE, SWAB DRY , GOT BACK @ 3 BBLS TOTAL FLUID. RELEASE PKR & COOH W/ TBG. PU SEATING NIPPLE & TAC. GIH W/ PROD TBG. RAN 135 JTS 2-3/8 TBG, TAC @ 4269', 12 JTS 2-3/8 TBG & S/ NIPPLE. EOT @ 4644'. ND BOP, NU WELL HEAD. SISD.

5/24/01---PU NEW PUMP & RUN RODS, LOAD TBG & CHECK PUMP ACTION, HANG WELL ON PRODUCTION, WELL TEST TO FOLLOW IN A FEW DAYS. RD POOL DDU. TEMP DROP FROM REPORT.

5/31/01---24 HR TEST, 3 BBLS OIL, 12 BBLS WATER, 13 MCF GAS.

6/1/01----24 HR TEST, 3BBLS OIL, 9 BBLS WATER, 14 MCF GAS.

6/2/01----24 HR TEST, 3 BBLS OIL, 5 BBLS WATER, 14 MCF GAS. DROP FROM REPORT.