

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30486
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
SOUTH Hobbs (GSA) Unit

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Amoco Production Company

8. Well No.
223

3. Address of Operator
P.O. Box 3092 Houston, Texas 77253

9. Pool name or Wildcat
Hobbs GSA

4. Well Location
Unit Letter **N** : **1791** Feet From The **WEST** Line and **1257** Feet From The **South** Line

Section **34** Township **18-S** Range **38-E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3613.2

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: **Supplemental Completion** ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose To: Squeeze Zone AND open NEW ZONES

**RUSH AND Pull Prod. Equip AND Tubing. RIH w/TBG AND Cement Retainer
SQUEEZE existing perfs 4050'-4090' 256 SX CLASS C. SHUT-IN 18 hours FOR
CEMENT TO SET. RIH AND Drill out CEMENT AND Pressure Test SQUEEZE. TAG
FLOAT collar at 4217' AND Drill out TO TD 4307'. RIH AND Perf 4256-4266,
4272-4288. RIH w/TBG AND Acidize Perfs. SWAB To Recover Load AND
Gauge TANK For Fluid ENTRY. RIH PERF @ 4100-4106, 4110-4130, 4160-4206,
4214-4244. ACIDIZE NEW Perfs. FLUSH w/50 BBL water AND POW TBG AND
PACKER. RET well TO Production For TEST.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **B. T. Steele** TITLE **Admin. Analyst** DATE **2-2-89**

TYPE OR PRINT NAME **Blake T. STEELE** TELEPHONE NO. **713-584-7321**

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

DATE **FEB 06 1989**

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: