

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LG 064198-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ CASH AREA

2. NAME OF OPERATOR
Fred Pool Drilling, Inc.

3. ADDRESS OF OPERATOR
P.O. Box 1393, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980 FSL & 1980 FEL Center of NW/4 SE/4 Unit J

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Lusk Federal

9. WELL NO.
#1

10. FIELD AND POOL, OR WILDCAT
Lusk (Yates) SR

11. SEC., T., R., OR BLK. AND SURVEY OR AREA
Sec. 18-T.19S-R.32E

14. PERMIT NO.
30-025-30500

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3584.7' GR

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☒
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We intend to Plug and Abandon the referenced well as follows:

1. Spot cement plug from PBTD (2800') to 2550' to cover perms, plus 100' above top perf. Tag this plug.
2. Spot cement plug from 1000 to 800', across shoe of surface casing, and top of salt section.
3. Spot 10 sx surface plug.
4. All plugs class "C" with mud between.
5. Clean and rehabilitate location and erect dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Michael J. Huska

TITLE Secretary

DATE 1/17/89

(This space for Federal or State office use)

APPROVED BY Michael J. Huska
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 1-27-89