

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
NM-93

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

APR 30 '90

2. NAME OF OPERATOR
Southland Royalty Company

8. FARM OR LEASE NAME
West Corbin Federal

3. ADDRESS OF OPERATOR
21 Desta Dr., Midland, TX 79705

3a. AREA CODE & PHONE NO.
**ARTESIA OFFICE
915/686-5600**

9. WELL NO.
13

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface **E**
660' FSL & 1980' FWL

10. FIELD AND POOL, OR WILDCAT
West Corbin (Bone Spring)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 18, T18S, R33E

14. PERMIT NO.
Approved 3/03/89

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3843' GR.

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Other) **Abandon Wolfcamp Zone**

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Continue new well completion--abandon the Wolfcamp zone and move uphole to the Bone Spring.
Set CIBP @10,795' and cap with 35' cement. New PBTD=10,760'.
Changed 3000 psi wellhead out and installed 5000 psi wellhead. Loaded and tested casing to 2000 psi.
Tested satisfactorily. Prepare to perforate and test the Bone Spring.

ACCEPTED FOR RECORD

As

APR 17 1990

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert L. Bradshaw

TITLE

Sr. Staff Env./Reg. Spec.

DATE

16 April 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side