

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30718

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
857948

7. Lease Name or Unit Agreement Name
VACUUM GRAYBURG SAN ANDRES UNIT

8. Well No.
158

9. Pool name or Wildcat
VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO PRODUCING INC.

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

4. Well Location
Unit Letter B : 660 Feet From The NORTH Line and 1330 Feet From The EAST Line

Section 1 Township 18-SOUTH Range 34-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3987', KB-3798'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU DA&S. CLEAN OUT TO PBTD OF 4980'. TEST CSG. TO 1500# FOR 30 MIN. PENWOOD RAN GR-CNL FROM 4980' TO 2800'. PERF w/ 2 JSPF: 4718-23, 4726-30, 4734-42, 4762-76, 4788-96. 78 HOLES. WESTERN ACIDIZED w/ 3900 GAL 15% NEFE. 7-1-90. SET RBP @ 4700'. TEST TO 3000#. BACKSIDE WOULD NOT HOLD.
2. ECP @ 1552' LEAKING. HALLIBURTON CEMENTED w/ 40 SX CLASS H @ 15.6ppg. DRILL OUT CMT. TEST CSG. TO 1000#. PENWOOD PERF w/2 JSPF: 4605-16, 4638-46, 4650-58, 4668-72, 4674-78, 4682-92. 90 HOLES. WESTERN ACIDIZED w/4500 GAL 15% NEFE. MOVE RBP TO 4580'. TEST TO 3000#.
3. PENWOOD PERF w/2 JSPF: 4431-50, 4461-66, 4483-4512, 4518-26, 4538-56. 158 HOLES. WESTERN ACIDIZED w/ 6300 GAL 15% NEFE. SWAB 7 HRS. REC 15 BNO & 105 BLW. MOVE RBP TO 4415' & TEST TO 3000#.
4. PENWOOD PERF w/2 JSPF: 4310-18, 4351-60, 4380-84, 4391-97, 4400-08. 70 HOLES. WESTERN ACIDIZED w/ 3000 GAL 15% NEFE. SWAB 5 HRS. REC 15 BNO & 120 BLW. MOVE RBP TO 4280' & TEST TO 3000#.
5. PENWOOD PERF w/2 JSPF: 4234-52. 36 HOLES. WESTERN ACIDIZED w/ 2200 GAL 15% NEFE. 7-15-90. ACIDIZED 7-17-90 w/ 3000 GAL 15% NEFE. HALLIBURTON FRAC w/ 3000 GAL XLG 1% KCL PAD & 1000 GAL XLG 1% KCL w/ 1 PPG 20/40 SAND. WASH SAND & TOH WITH RBP.
6. RAN 2 7/8 TUBING AND SUB PUMP. 7-24-90.
7. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE DRILLING SUPERINTENDENT DATE 07-25-90

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: