Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aziec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO. 30-025-30722

5. Indicate Type of Lease

STATE FEE

6. State Oil & Gas Lease No.

1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
I. Type of Well:  OR. GAS  WELL OTHER	New Mexico State "W"
2. Name of Operator  Questa Oil + Gas Co.  3. Address of Operator	8. Well No.
4. Well Location South Yale, Suite 700, Tulsa, OK 74/36-3718	9. Pool name or Wildcat  Yacuum (Grayburg San Andre
Unit Letter P: 330 Feet From The South Line and 87	Feet From The <u>East</u>
Section 13 Township 17-5 Range 34-F	NMPM Lea Count
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea Count
11. Check Appropriate Paul & Ludius No.	
MOTICE OF INTENTION TO	eport, or Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	<del></del>
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. DLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CE OTHER:	
OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.	ing estimated date of starting any proposed
1). Pull out of hole with Production Equipment. 2). Set 41/2" CIBP at 4400' and cap W/35' Cement. 3). Load hole W/mud.	
t). Spot 23 sacks of Cement plug at 3190'. 5). Cut and Pull 41/2" casing from approx. 2500'.	
S). Spot 25 sacks of cement plug at 4½" stub approx. 2500' to 30 sacks of cement plug at 83/8" shoe 1704' 50' in 8). Spot 10 sacks of cement at surface plug and set up surface plug at 83/8"	For W.O.C. and Tag. 50' out, W.O.C. and Tag.
Proposed start bate 9/22/93	TO SEE THE SECOND SECON
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SKINATURE

TYPE OR PRINT NAME

See Control of the best of my knowledge and belief.

TYPE OR PRINT NAME

TELEPHONE NO. 806-894-6008

TITLE

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

SEP 23 1993

BECEIVE

SEP 8 5 1993

OUD FETOS