

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30755
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857948
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No.	139
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1282</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>18S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4006' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	DRILL CIBP & ACIDIZE <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-23-00: MIRU. NDWH. NUBOP. START PULLING TBG. SWAB TBG DRY.  
10-24-00: TAC @ 4172. SN @ 4651'. TIH W/BIT, DC'S. PU WS. STOP BIT @ 4311'.  
10-25-00: PU TBG & TAG @ 4708'. PULL BIT TO 3429'.  
10-26-00: MIRU FOAM UNIT. TAG PLUG @ 4707. START DRLG PLUG @ 1:30 PM. DRILL PLUG IN 3 HRS. PUSH TO 4725'. DRILL @ 4725'.  
10-27-00: DRILL 4725-4732. RIG DOWN FOAM UNIT.  
10-28-00: TIH W/BIT & CSG SCRAPER TO 4342'.  
10-30-00: TIH W/PKR, & TBG. PSA 4174'. LOAD/TEST CSG TO 500-OK. ACIDIZE PERFS 4347-4732 W/6000 GALS 15% NEFE ACID.  
10-31-00: MADE 6 SWAB RUNS. END FL @ 3900. REL PKR. TIH W/BIT TO 4732'. NO FILL.  
11-01-00: TIH W/OPMA, GA, SN, TBG & TAC. MA @ 4698'. SN @ 4658'. TAC @ 4146'. TIH W/PMP & RDS. HANG WELL ON. LOAD/TEST.  
11-06-00: RIG DOWN.  
11-20-00: ON 24 HR OPT. PUMPED 40 BO. 340 BW. & 20 MCF. PERFS 4347-4806.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 12/5/00  
TYPE OR PRINT NAME J. Denise Leake Telephone No. 997-0405  
688-4752

(This space for State Use)

APPROVED \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY \_\_\_\_\_ TITLE \_\_\_\_\_