

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30755
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857948
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No.	139
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4006' GR

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1282</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>18S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4006' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Set CIBP & Acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-17-99: ATTEMPT TO UNSEAT PUMP. STUCK IN SN. SWAB TBG DN. NDWH, NUBOP. REL TAC.
8-18-99: TIH W/TBG. TAG @ 4715'. TIH W/CIBP, & TBG. SET CIBP @ 4700'. TIH W/PKR, SN, TBG. PSA 4282'. LOAD & PSI CSG TO 500 PSI-OK.
8-19-99: ACIDIZE VGSAU PERFS 4347-4678' W/5000 GALS 15% NEFE HCL ACID & 4500# RK SLT. RU SWAB. FL @ 3800'. PUMP 165 GALS TH-756 MIXED W/30 BFW.
8-20-99: REL PKR. TIH TO 4700'. TAG CIBP-NO FILL. TIH W/OPSMA, SN, TBG, TAC. MA @ 4668'. SN @ 4637'. TAC @ 4247'. TIH W/GAS ANCHOR, PUMP, SNKR BARS & RDS.
8-21-99: HANG ON. LOAD & TEST TO 500#-OK. CHECK PUMP ACTION. RIG DOWN. PUMPING @ 3:30 PM.
8-30-99: ON 24 HR OPT. PUMPED 66 BO, 342 BW, & 24 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 08/30/1999

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY Paul Kautz Geologist TITLE Geologist DATE 08/30/1999

CONDITIONS OF APPROVAL, IF ANY: