

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30762
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 546850
7. Lease Name or Unit Agreement Name NEW Mexico "CR" STATE
8. Well No. 5
9. Pool name or Wildcat WILDCAT

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator TEXACO INC.	
3. Address of Operator P.O. Box 3109 MIDLAND, TEXAS 79702	
4. Well Location Unit Letter K : 1930 Feet From The SOUTH Line and 2310 Feet From The WEST Line Section 32 Township 19-SOUTH Range 32-EAST NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3528'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) MIRU DASH WELL SERVICE. POH + Laydown Pump + Rods. TOH with Tubing.
2) By ROTARY WIRELINE SET 5 1/2" CIBP @ 2600'. Dump 4 sxs CEMENT on PLUG. TOC @ 2560'.
3) TH to 2500'. WESTERN DISPLACED HOLE WITH 25# GELLED BRINE
4) Pull up to 950' + SPOT 20 sxs CLASS 'H' FROM 950' to 850'.
5) Pull up to 50' + SPOT 10 sxs CLASS 'H' FROM 50' to SURFACE
6) CUT OFF WELL HEAD + INSTALL DRY HOLE MARKER 2-2-90

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Drilling Superintendent DATE 2-6-90

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____