

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30797
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 857948
7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No. 141
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator TEXACO PRODUCING INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter <u>E</u> : <u>1309</u> Feet From The <u>WEST</u> Line and <u>1980</u> Feet From The <u>NORTH</u> Line Section <u>1</u> Township <u>18-SOUTH</u> Range <u>34-EAST</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4000', KB-4013'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: COMPLETING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- PENWOOD PERF w/ 2 JSPF: 4680-85, 4694-4705 32 HOLES. DOWELL ACIDIZED w/ 1435 GAL 15% NEFE. 6-6-90. SWAB 4 HRS. 6-8-90, REC 5 BNO & 78 BFW. TIH AND SET RBP @ 4485'. TEST TO 3000#.
- PENWOOD PERF w/ 2 JSPF: 4432-40, 4446-54, 4464-70. 48 HOLES. DOWELL ACIDIZED w/ 2000 GAL 15% NEFE. SWAB 2.5 HRS 6-11-90. REC 11 BLW & 48 BFW. RESET RBP @ 4420'. TEST TO 3000#.
- PENWOOD PERF w/ 2 JSPF: 4302-06, 4312-18, 4324-28, 4334-4353, 4365-76, 4386-88, 4392-98. 104 HOLES. DOWELL ACIDIZED w/ 4400 GAL 15% NEFE. 6-12-90. SWAB 6 HRS. REC 74 BLW.
- MOVE RBP TO 4285'. TEST TO 3000#. COMPUTALOG PERF w/ 2 JSPF: 4258-4275. 34 HOLES. DOWELL ACIDIZED w/ 2000 GAL 15% NEFE. 6-14-90. SWAB 10 HRS. REC 12 BNO, 18 BLW & 154 BW.
- TOH WITH RBP. RAN TUBING, PUMP & RODS. SN @ 4759'.
- PUMP AND TEST.
- PREP TO POTENTIAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE DRILLING SUPERINTENDENT DATE 06-25-90
TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 29 1990