

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30801
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 857948
7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No. 154
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4000', KB-4013'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator TEXACO PRODUCING INC.
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>1331</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>18-SOUTH</u> Range <u>34-EAST</u> NMPM LEA County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TIH & SET RBP @ 4720'. TEST TO 3000#. WEDGE PERFERED w/ 2 JSPF: 4618-24, 4632-36, 4640-45, 4668-78, 4696-4706. 70 HOLES. DOWELL ACIDIZED w/ 3700 GAL 28% NEFE. 5-11-90. SWAB 4 HRS. REC 119 BFW & 30% OIL CUT. MOVE RBP TO 4592'. SET & TEST TO 3000#.
2. PENWOOD PERF w/ 2 JSPF: 4536-40, 4560-68. 24 HOLES. DOWELL ACIDIZED w/ 1500 GAL 28% NEFE. 5-14-90. SWAB 5 HRS. REC 99 BFW & 5% OIL CUT. MOVE RBP TO 4520'. SET & TEST TO 3000#.
3. PENWOOD PERF w/ 2 JSPF: 4424-27, 4437-45, 4455-64, 4470-74, 4480-82, 4486-96, 4500-06. 84 HOLES. DOWELL ACIDIZED w/ 4500 GAL 28% NEFE. 5-18-90. SWAB 5 HRS. REC 31 BNO, 65 BLW & 66 BFW.
4. MOVE RBP TO 4400'. SET & TEST TO 3000#. PENWOOD PERF w/ 2 JSPF: 4326-30, 4354-60, 4364-71, 4380-84, 4390-94. 50 HOLES. DOWELL ACIDIZED w/ 2700 GAL 28% NEFE. 5-20-90. SWAB 10 HRS. REC 43 BLW.
5. UNSET RBP & TOH. TIH w/ 2 7/8 TUBING, PUMP & RODS. SN @ 4858'. 5-23-90.
6. RAN REDA SUB-PUMP 6-2-90.
7. PREP TO PUT ON POTENTIAL TEST.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE DRILLING SUPERINTENDENT DATE 06-05-90

TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JUN 12 1990