

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30803
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEB <input type="checkbox"/>
6. State Oil & Gas Lease No. 857948
7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No. 152
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4019', KB-4032'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator TEXACO PRODUCING INC.
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	4. Well Location Unit Letter D : 640 Feet From The NORTH Line and 1310 Feet From The WEST Line Section 2 Township 18-SOUTH Range 34-EAST NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4019', KB-4032'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: COMPLETING <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TIH SET RBP AT 4700' AND TESTED TO 3000#.
2. PENWOOD PERFED 4590'-94', 4599'-4612', 4620'-26', 4636-44, 2 JSPF, 66 HOLES.
3. DOWELL ACIDIZED w/ 2000 GAL 28% NEFE.
4. RELEASE RBP. TOH. TIH WITH NEW RBP AND SET AT 4580'. TEST TO 3000#.
5. PENWOOD PERFED 4544'-47', 4552'-58', 4564'-70'. 2 JSPF, 30 HOLES.
6. DOWELL ACIDIZED w/ 1500 GAL 28% NEFE. SWAB 4 HOURS REC 36 BLW 4-21-90.
7. RAN TUBING, PUMP, AND RODS.
8. PUMPED 14 HOURS REC 1 BNO ANS 270 BLW 4-23-90.
9. TESTING

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE DRILLING SUPERINTENDENT DATE 04-25-90  
TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APR 30 1990

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: