

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30917
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 857948
7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No. 150
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator TEXACO PRODUCING INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter <u>G</u> : <u>1390</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>1</u> Township <u>18-SOUTH</u> Range <u>34-EAST</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3991', KB-4004'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: COMPLETING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. DA&S CLEAN OUT TO PBTD OF 4798'. TEST CSG. TO 3000#. PENWOOD RAN GR-CCL FROM 4798' TO 4000'.
2. PERF w/ 2 JSPF: 4479-88, 4502-05, 34-40, 48-55, 60-62, 66-70, 74-77, 84-88, 95-97, 4602-06, 16-21, 62-68, 73-75, 78-4682. 116 HOLES. WESTERN ACIDIZED w/ 7000 GAL 15% NEFE.
3. SET RBP @ 4470'. TEST TO 3000#. PERF w/ 2 JSPF: 4289-94, 4305-10, 22-28, 38-45, 86-94, 4403-10, 37-42, 50-52, 58-4462. 98 HOLES. WESTERN ACIDIZED w/ 5200 GAL 15% NEFE. MOVE RBP TO 4271'. TEST TO 3000#.
4. PERF w/ 2 JSPF: 4137-45, 86-90, 96-4204, 4234-37, 42-47, 50-4254. 64 HOLES. WESTERN ACIDIZED w/ 4100 GAL 15% NEFE.
5. SWAB 5 HOURS 8-29-90. RECOVERED 15 BNO & 134 BLW.
6. TOH WITH RBP. TIH WITH 2 7/8 TUBING AND SUB PUMP.
7. TESTING. PREP TO POTENTIAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / CWK TITLE DRILLING SUPERINTENDENT DATE 09-07-90

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

APPROVED BY APPROVED BY JERRY SEXTON
APPROVED BY JERRY SEXTON

TITLE APPROVED BY JERRY SEXTON DATE APPROVED BY JERRY SEXTON

CONDITIONS OF APPROVAL, IF ANY: