

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31073
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-11
7. Lease Name or Unit Agreement Name Hourglass State Unit
8. Well No. 1
9. Pool name or Wildcat Mid Vacuum Bone Springs
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3919' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line Section 16 Township 18S Range 35E NMFM Lea County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Recompletion to Bone Springs</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-14-94 - Moved in and rigged up pulling unit. TOOH with sub pump. Rigged up wireline. Ran 4.5" OD gauge ring and junk basket to 9920'. TOOH. TIH and set CIBP at 9918' and capped with 35' of cement.

1-15-94 - WIH and perforated 9728-9732' w/10 .42" holes (Bone Springs). TIH w/5-1/2" 20-23# Uni V packer to 9664'. Loaded hole. Set packer and pressured to 5000#. Perforations did not break. Released packer and moved down. Respot acid across perforations. Pull up and set packer. Perforations on vacuum. Acidized perforations 9728-9732' with 500 gallons 20% NEFE acid. Swabbed.

1-16-94 - Swabbing.

1-18-94 - Released packer and TOOH. Laid down 40 joints of 2-7/8" N-80 new tubing. TIH with mud anchor, perforated sub, seating nipple, 2 joints, tubing anchor catcher and remaining tubing. Strip off BOP. Set tubing anchor catcher at 7936' with seating nipple at 8000'. Released to production to run pump and rods.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-24-94

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 26 1994

CONDITIONS OF APPROVAL, IF ANY: