

Submit 3 Copies To Appropriate District Office

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <b>30-025-31155</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>VF-0395</b>
7. Lease Name or Unit Agreement Name: <b>Buckeye 12 State</b>
8. Well No. <b>#1</b>
9. Pool name or Wildcat <b>Dos Amigos Wolfcamp</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator <b>Harvey E. Yates Company</b>	
3. Address of Operator <b>P.O. Box 1933, Roswell, New Mexico 88202</b>	
4. Well Location Unit Letter <b>F</b> : <b>1,980</b> feet from the <b>North</b> line and <b>1,980</b> feet from the <b>West</b> line Section <b>12</b> Township <b>18S</b> Range <b>35E</b> NMPM <b>Lea</b> County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3883' GR</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

10/11/2000 Set CIBP @ 8,050' w/4 sxs cement on top. Circulate 10# mud. Spot 25 sxs cement @ 5,428-5,178'. Spot 25 sxs cement @ 3,509'.  
10/12/2000 Cut csg @ 2,400'. Spot 75 sxs cement @ 2,450-1,700'. Cut csg @ 1,000. Cut csg @ 500'.  
10/13/2000 Lay down 12 jts 5 1/2" csg. Spot 25 sxs cement @ 1,050'. Spot 35 sxs cement @ 550'. Tag @ 420'. Spot 10 sxs cement @ surface. Install dry hole marker. Clean location. P&A complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianna Rodgers TITLE Production Analyst DATE 11/10/00

Type or print name Dianna Rodgers Telephone No. 505-623-6601  
(This space for State use)

APPROVED BY Johnny Robinson TITLE Oil Conservation Director DATE 11/04/01  
Conditions of approval, if any: