

OIL CONSERVATION DIVISION

**DISTRICT I**  
P. O. Box 1980 Hobbs, NM 88240

**DISTRICT II**  
P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd, Aztec, NM 87410

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

Well API NO.	30-025-31155
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VB-0395
7. Lease Name or Unit Agreement Name	BUCKEYE 12 STATE
8. Well No.	# 1
9. Pool name or Wildcat	DOS AMIGOS WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601	4. Well Location Unit Letter <u>F</u> : <u>1,980</u> Feet From The <u>NORTH</u> Line and <u>1,980</u> Feet From The <u>WEST</u> Line Section <u>12</u> Township <u>18S</u> Range <u>35E</u> NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3882. 5' GR ( 14. 5' KB )</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <u>RESUBMITTAL FOR P&amp;A</u> <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

CURRENT PERFS: 8084-96'  
UNI-V PACKER @ 8000'

1. CIBP @ 8050' + 35' CMT
2. 100' CMT @ 5414' (TOP OF SAN ANDRES)
3. 100' CMT @ 3500' (ACROSS INTER. SHOE & BOT. OF SALT) TAG
4. ATTEMPT TO RECOVER 2400' OF CASING.
5. PUMP 50' CMT IN AND OUT OF STUB. TAG
6. 100' CMT @ 1800' (TOP OF SALT) (TAKES PLACE OF SURFACE SHOE PLUG)
7. 50' SURFACE PLUG. INSTALL DRY HOLE MARKER

CALL OCD-I @ 1-505-393-6161 24 HOURS PRIOR TO COMMENCEMENT OF OPERATIONS.  
ABOVE APPROVED BY PAUL KAUTZ OCD-I 7-9-96RFN

NOTE THIS WELL IS HIGHLY H2S (APPROX.  
18,000PPM). TAKE NECESSARY SAFETY  
PRECAUTIONS FOR PROTECTION.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Ray F. Nokes</u>	TITLE	<u>PROD. MGR. / ENGINEER.</u>	Date	<u>11/10/99</u>
TYPE OR PRINT NAME	<u>RAY F. NOKES</u>	TELEPHONE NO.	<u>1-505-623-6601</u>		

(This space for State use)

Approved by	<u>RECEIVED</u>	Title	<u>RECEIVED</u>	Date	<u>11/10/99</u>
Conditions of approval, if any:					

✓  
do