

OIL CONSERVATION DIVISION

DISTRICT I
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-025-31155
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VB-0395
7. Lease Name or Unit Agreement Name	BUCKEYE 12 STATE
8. Well No.	# 1
9. Pool name or Wildcat	Dos Amigos Wolfcamp UNDESIG WILDCAT

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601	4. Well Location Unit Letter <u>F</u> : <u>1,980</u> Feet From The <u>NORTH</u> Line and <u>1,980</u> Feet From The <u>WEST</u> Line Section <u>12</u> Township <u>18S</u> Range <u>35E</u> NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3882. 5' GR (14. 5' KB)</u>
---	--	---	---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>CASING INTEGRITY TEST FOR 5 YR TA APPROVAL</u> <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

CALLED OCD-1 5-28-97 FOR NOTICE OF TEST.
MI & RU ON 5-30-97. RU WEDGE & RUN 5 1/2" CIBP TO 8050' & SET.
RUN IN HOLE w/ TBG OPEN ENDED TO 7994' & NIPPLE UP WELL HEAD.
CIRC HOLE w/ OXYGEN SCAVENGER & CORROSION INHIBITOR.
PLUG OFF VALVES TO INSURE NO LEAKS.
PRESSURE CASING TO 620#s FOR 30 MINUTES. HELD OK. LOST 10#'s. BLED OFF
RIG DOWN & REL PU & HUGHES.

TEST COMPLETED FOR CASING INTEGRITY. REQUEST 5 YR APPROVAL FOR TA STATUS

PERMISSION TO TEST GIVEN
ABOVE APPROVED BY PAUL KAUTZ OCD-I 5-28-97RFN

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Ray F. Nokes</u>	TITLE	<u>PROD. MGR. / ENGINEER.</u>	Date	<u>5/31/97</u>
TYPE OR PRINT NAME	<u>RAY F. NOKES</u>	TELEPHONE NO.	<u>1-505-623-6601</u>		

(This space for State use)
Orig. Signed by
Paul Kautz
Geologist

Approved by		Title		Date	<u>JUN 04 1997</u>
-------------	--	-------	--	------	--------------------

Conditions of approval, if any:

This Approval of Temporary
Abandonment Expires 5/31/2002

JCSB

CP

