Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, ...inerals and Natural Resources Department

Form C-103 Revised 1-1-89

Santa Fe, New Mexico 87504-2088  5. Indicate Type of Lasse STATE S	P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-025 31187-0000
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERN OR PLUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT"  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERN OR PLUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT"  (T) Type of Well:	DISTRICT II P.O. Drawer DD, Anesia, NM 88210  Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG RACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"   FORM G-101) FOR SUCH PROPOSALS.		
ONLY WILL STAND CHARLES R. QUALIA  2. Name of Operator CHARLES R. QUALIA 3. Address of Operator P O. BOX 10181 MIDLAND. TEXAS 79702  4. Well Location Unit Letter : 1980 Feet From The FNL Line and 1980 Feet From The FWL Line Section 1 Township T-18-S Range R-35-E NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3888 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REPORT OF: SUBSEQUENT REPORT OF: PULL OR ALTER CASING CHANGE PLANS CASING CASING CHANGE PLANS CASING TEST AND CEMENT JOB  OTHER: OTHER: OTHER: OTHER 12. Describe Proposed or Completed Operations (Clearly state all perineen details, and give perineen dates, including estimated date of starring any proposed work) SEE RULE 19.  (1) CIEB 10. 5600. 5.1/2 W/35 Cement or 100 Cement plug WOC and TAG (2) 35sx 3900 3700 TOTHER (3) 40sx 510.400. (3) 40sx 510.400. (5) 10sx Surf. Install dry hole market  (Champer for State Use) CRASH SCHOOL SC	( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	(
CHARLES R. QUALIA  3. Address of Operator P. O. BOX 10181 MIDLAND TEXAS 79702  4. Well Location Unit Letter F: 1980 Feet From The FNL Line and 1980 Feet From The FWL Line Section 1 Township T-18-S Range R-35-E NMPM Lea County 10. Elevation (Now whether DF. RKB, Rf, GR, etc.) 3888 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: T12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  (1) CIBP @ 5600- 5 1/2 W/35' Cement or 100' Cement plug WOC and TAG (2) 35sx 3900-3700 (3) 40sx 5-1/2 csg stub 3500 f. (4) 40sx 5-1/2 csg stub 3500 f. (4) 40sx 5-10-410 (5) 10sx Surf. Install dry hole marker  (District) But the information above is truefled complete to the best of my troovings and belief.  Therefore first the Use Confidence of the Starting and Page 15 f.  The REPORT OF TABLES OF TABLES OF TABLES SEXTON  CONTINUE ALTER ASSISTED.  The REPORT OF TABLES SEXTON  CONTINUE ALTER ASSISTED.  THE AGE OF TABLES SEXTON  CONTINUE ALTER ASSISTED.  CONTINUE ALTER ASSISTED.  CONTINUE ALTER ASSISTED.  CONTINUE ALTER ASSISTED.  APR 0.7 1995	1 OT	
3. Address of Operator   P. O. BOX 10181 MIDLAND. TEXAS 79702   Wildcat	1	
Well Location   Line and 1980   Feet From The   FNL   Line and 1980   Feet From The   FWL   Line		
Unit Letter		Wildcat
10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:  DILLOR ALTER CASING OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  (1) CIBP \$ 5600 - 5 - 1/2 W/35 cement or 100 cement plug WOC and TAG (2) 35sx 3900 - 3700 (3) 40sx 5 1/2 csg stub 3500 - 4(4) 40sx 5 10 - 410 (5) 10sx Surf. Install dry hole marker  9 5 mud between all plugs  Thereby centry that the information above is traying complete to the bost of my browledge and belief.  SIGNATURE Agent Described by ERRY SEXTON COMMENCE For State Use) CHARLES OF SEXTON  COMMENCE DF. REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRIVEN SEXTON  COMMENCE DF. REPORT OF:  REMEDIAL WORK ALTERING CASING CASHING CA		Feet From The FWL Line
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS.  PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB CHANGE PLOY.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  (1) CIBP § 5600 - 5 1/2 W/35 cement or 100 cement plug WOC and TAG (2) 35sx 3900 3700 (3) 40sx 5-1/2 csg stub 3500 (4) 40sx 510 410 (5) 10sx Surf. Install dry hole marker  9 5 mud between all plugs  Thereby certify that the information above is truyfind complete to the logic of my browledge and belief.  SKINATURE Agent DATE 4-6-95 (915)  TYPE OR PRINT NAME W. L. Holmes RAPE SEXTON CONSTITUTE STATE STATE STATE APP 0.7 1995	10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OF COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:    CASING TEST AND CEMENT JOB OTHER:		eport, or Other Data
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  PULL OR ALTER CASING  OTHER:	NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PULL OR ALTER CASING  OTHER:	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
OTHER:    OTHER:   OTHER:	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  (1) CIBP @ 5600- 5-1/2 W/35 cement or 100 cement plug WOC and TAG (2) 35sx 3900 - 3700 (3) 40sx 5-1/2 csg stub 3500 + (4) 40sx 510 - 410 (5) 10sx Surf. Install dry hole marker  9 5 mud between all plugs  I hereby certify that the information above is true find complete to the loss of my knowledge and belief.  SIGNATURE Agent part Agent part Agent (915)  TYPE OR PRINT NAME W. L. Holmes (915)  TYPE OR PRINT NAME W. L. Holmes Agent Agent Applications of the loss of the l	PULL OR ALTER CASING CASING TEST AND C	EMENT JOB
Work) SEE RULE 1103.  (1) CIBP @ 5600- 5-1/2 W/35' cement or 100' cement plug WOC and TAG  (2) 35sx 3900'-3700' (3) 40sx 5-1/2 csg stub 3500 **  (4) 40sx 510'-410' (5) 10sx Surf. Install dry hole marker   9 5 mud between all plugs  Thereby certify that the information above is true-field complete to the bost of my knowledge and belief.  SIGNATURE		
Work) SEE RULE 1103.  (1) CIBP @ 5600- 5-1/2 W/35' cement or 100' cement plug WOC and TAG  (2) 35sx 3900'-3700' (3) 40sx 5-1/2 csg stub 3500 **  (4) 40sx 510'-410' (5) 10sx Surf. Install dry hole marker   9 5 mud between all plugs  Thereby certify that the information above is true-field complete to the bost of my knowledge and belief.  SIGNATURE	OTHER: OTHER:	
(2) 35sx 3900 - 3700 - (3) 40sx 5-1/2 csg stub 3500 - (4) 40sx 5-1/2 csg stub 3500 - (4) 40sx 5-10 - 410 - (5) 10sx Surf. Install dry hole marker  9 5 mud between all plugs  Thereby certify that the information above is true and complete to the boat of my knowledge and belief.  SIGNATURE Agent DATE 4-6-95 - (915)  TYPEOR PRINT NAME W. L. Holmes (915)  TYPEOR PRINT NAME W. L. Holmes (915)  TYPEOR PRINT NAME W. L. Holmes Agent Agent (915)  TELEPHONE NO. 570-2721		dine estimated date of startine any proposed
Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incli-	ding estimated date of starting any proposed
married agreevisor	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.  (1) CIBP @ 5600- 5-1/2 W/35 cement or 100 ceme (2) 35sx 3900 - 3700 + (3) 40sx 5-1/2 csg stub 3500 - (4) 40sx 510 - 410	, , , ,
	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.  (1) CIBP @ 5600- 5-1/2 W/35 cement or 100 ceme (2) 35sx 3900 - 3700	nt plug WOC and TAG  DATE 4-6-95 (915)