

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-31353
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. Fee lease
7. Lease Name or Unit Agreement Name: EKAY 28 STATE
8. Well No. 2
9. Pool name or Wildcat DIOS MANO BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Harvey E. Yates Company

3. Address of Operator
P.O. Box 1933, Roswell, New Mexico 88202

4. Well Location

Unit Letter P : 660 feet from the SOUTH line and 660 feet from the EAST line

Section 28 Township 18 S Range 34 E NMPM County LEA

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4019.8' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ADD PERFORATIONS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

02/27/2003 DAY 01, MI RU SMITH & MARRS. ND WH & NU BOP. POOH W/LOCK SET PACKER & 276 JTS 2 3/8" TBG.

02/28/2003 DAY 02, GIH W/CMT RETAINER & 275 JTS 2 3/8" TBG TO 9030' & SET RETAINER. DUMP 30' CMT ON TOP OF RETAINER. LOAD HOLE W/9# MUD. PULLED UP TO 6100' AND SPOT 25 SX CMT. PULLED UP TO 3525' AND SPOT 25 SX CMT AND POOH W/TBG.

03/01/2003 DAY 03, GIH W/2 3/8" TBG TO TAG CMT PLUG (TAG UP @ 3261'). GIH TO 1950' & CUT OFF CSG. POOH LAYING DN 45 JTS N-80 5 1/2" CSG. GIH W/2 3/8" TBG TO 2000' AND SPOT 40 SX CMT. SDFWE.

03/04/2003 DAY 06, GIH W/2 3/8" TBG, TAG CSG STUB PLUG @ 1818'. PULLED UP HOLE TO 400'. SPOT 35 SX CMT. WOC. TAGGED UP @ 296'. PULLED UP & SPOT 20 SX CMT FOR SURFACE PLUG. INSTALL DRY HOLE MARKER. RD & CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 2/28/03

Type or print name Jeanetta Atkinson

Telephone No. 505-623-6601

(This space for State use)
ORIGINAL SIGNED BY GARY W. WINK

APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGER TITLE

MAR 19 2003
DATE

Conditions of approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.