

Form 1004-1
November 1984
Formerly 1004-1

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Budget Estimate No. 1004-1
Expires April 11, 1985

LEASE DESIGNATION AND FIELD

LC-069276

IF INDIAN ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

FARM OR LEASE NAME

Hudson Federal

WELL NO.

5

FIELD AND POOL, OR WILDCAT

Undesig. Buffalo Queen

SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 29, T-18-S, R-33-E

COUNTY OR PARISH STATE

Lea

N.M.

SUNDRY NOTICES AND REPORTS ON RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Robert N. Enfield

ADDRESS OF OPERATOR

P. O. Box 2431, Santa Fe, New Mexico 87501

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 1980' FWL of Section 29

PERMIT NO.

ELEVATIONS (Show whether DF, RT, GR, etc.)

2470.16' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

Note: Plan to run 4.50", 11.60#/ft. casing and cement with 800 sx. HLC plus 300 sx. 50/50 Poz; this
will provide fill in excess of the APD requirements or circulate cement to the surface. X-

Completion Plans

1. Prepare road and location for completion operations.
2. Run PDC log then perforate at 4,398', 4,400', 4,416', 4,420' & 4,425' KB with
2- 0.37" holes (10 holes).
3. Break perforations; swab and flow to test; acidize with 1000 gal. acid, swab to test.
4. Fracture treat with recommended volumes and materials based upon swab test after acid.
5. Flow/swab to test.
6. Install production equipment (tanks, heater-treater, pumping unit, etc.).
7. Run potential test; initiate production.

* (Called in) to Hobbs office,
9/23/91. JTC

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the
United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.