Submit 3 Copies to Appropriate
District Office

APPROVED BY-

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

- DATE -

DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	
	5 indicate 1 vpe of Lease
DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. IG - 2945
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC	CK TO A 7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name of Omit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	Maralo SV 16 State
Type of Well: OIL GAS	
WELL X WELL OTHER	
. Name of Operator	8. Well No.
Maralo, Inc.	2
Address of Operator	9. Pool name or Wildcat
P. O. Box 832, Midland, Texas 79702 0832	Wildcat
. Well Location	
Unit Letter :2310 Feet From The West Line and	i 530 Feet From The North Line
Section 16 Township 18S Range 35E	NMPM Lea County
Section 16 Township 18S Range 35E	
//////////////////////////////////////	
	otice Penort or Other Data
	· · · · · · · · · · · · · · · · · · ·
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	NORK ALTERING CASING
MPORARILY ABANDON CHANGE PLANS COMMENCE	DRILLING OPNS. DPLUG AND ABANDONMENT
JLL OR ALTER CASING CASING TES	ST AND CEMENT JOB
	STAND CEMENT GOD
THER: OTHER:	
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent	dates, including estimated date of starting any proposed
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103.	
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carri	er gun loaded w/premium charges &
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599	er gun loaded w/premium charges & ', 10,600' (10 total holes)
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water.
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrists shot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumpe	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/f
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/fi
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumpeto 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 2-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 2-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumperto 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First
2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumpeto 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 2-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 2-11-91 Swabbed down. Unset pkr. 2-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on with the stayed in the stayed of the stayed in t	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/fi ,450' w/ 10,000#. FL @ 3900'. First CIBP.
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 2-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 2-11-91 Swabbed down. Unset pkr. 2-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 2-13-91 Spot 200 gals 15% NEFE triple inhibited acid.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ff ,450' w/ 10,000#. FL @ 3900'. First CIBP. And The Company of the CIBP. RIH w/4" carrier gun. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 2-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599 2-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 2-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 2-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 2-11-91 Swabbed down. Unset pkr. 2-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 0.2-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 1	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on experiment work) spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 1	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 0.2-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 1.2-14-91 Ran tbg & pkr in hole to 9885. Swabbed	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599. 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 2-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 1. 12-14-91 Ran tbg & pkr in hole to 9885. Swabbed	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft 0,413', total 12 holes.
2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 12-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 11.2-14-91 Ran tbg & pkr in hole to 9885. Swabbed I hereby certify that the information above is true and complete to the best of my knowledge and belief.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft 0,413', total 12 holes. Quellar /-/3-9.2
2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 12-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 112-14-91 Ran tbg & pkr in hole to 9885. Swabbed I hereby certify that the information above is true and complete to the best of my knowledge and belief.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft 0,413', total 12 holes.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. 12-5-91 Ran cmt bond log 10,693-4700'. WIH w/4" carrishot 2 SPF @ 10,596', 10,597', 10,598',10,599 12-7-91 Swabbed 136 bbls total fluid 10 BO + 126 BW. 12-9-91 Swabbed 100% water. Set CIBP @ 10,570'. Dumper to 10,332'. Spot 200 gals 15% NEFE acid. TO 10,502',10503',10,531',10,532, total 8 holes. 12-10-91 TIH w/341 jts 2 3/8" tbg. + pkr. Set pkr @ 10 run FL stayed @ 5200'. 12-11-91 Swabbed down. Unset pkr. 12-12-91 Set CIBP on WL @ 10,460'. Dumped 2 sx cmt on 12-13-91 Spot 200 gals 15% NEFE triple inhibited acid. 10,408', 10409', 10,410', 10,411', 10,412', 1 12-14-91 Ran tbg & pkr in hole to 9885. Swabbed Thereby certify that the information above is true and complete to the best of my knowledge and belief.	er gun loaded w/premium charges & ', 10,600' (10 total holes) Last 2 runs all water. d 2 sx cmt on top w/bailer. TIH w/tbg H w/tbg. RIH w/Apollo. Shot 2 holes/ft ,450' w/ 10,000#. FL @ 3900'. First CIBP. RIH w/4" carrier gun. Shot 2 holes/ft 0,413', total 12 holes. Queller 1-/3-9.2

- TITLE -