

17. Cut off all casing 3' below ground level. Cap with abandonment marker. Restore location as directed.

Recommend: \_\_\_\_\_  
Paul Neumeister, Engineer II

\_\_\_\_\_  
Date

Approve: \_\_\_\_\_  
Cash Smithwick, Drilling Superintendent

\_\_\_\_\_  
Date