

OIL CONSERVATION DIVISION

DISTRICT I

P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-025-31526
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-2252
7. Lease Name or Unit Agreement Name EKAY 27 STATE	
8. Well No.	# 1
9. Pool name or Wildcat	SWD AIRSTRIP BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input type="checkbox"/> GAS <input type="checkbox"/> SWD WELL WELL OTHER	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601
4. Well Location Unit Letter M : 660' Feet From The SOUTH Line an 660' Feet From The WEST Line Section 27 Township 18S Range 34E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4012. 5' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

7-12-96 SET CIBP @ 9040' & SPOT 25 SKS CEMENT ON TOP. TOP OF CEMENT @ 8850'.  
7-15-96 CIRC 10 # MUD & SPOT 25 SKS @ 7860 TO 7650'  
PULL TO 3500 & SPOT 25 SKS CEMENT FROM 3500 TO 3300'.  
7-16-96 CUT CASING @ 2380'. UNABLE TO PULL OR PUMP INTO CUT. SPOT 30 SK PLUG  
FROM 2430 TO 2180'. CUT CASING @ 1500'. UNABLE TO PULL OR PUMP INTO CUT.  
SPOT 25 SK PLUG FROM 1550 TO 1350'. CUT CASING @ 550'. UNABLE TO PULL OR  
PUMP INTO CUT. SPOT 30 SK PLUG FROM 600 TO 400'. SPOT 10 SK SURFACE PLUG FROM  
60' TO SURFACE. (NOTE: WITNESSED BY OCD)  
7-17-96 INSTALL DRY HOLE MARKER. COVER PITS, CUT OFF ANCHORS. INSTALL DRY HOLE  
MARKER. CLEAN LOCATION, BACKFILL WORK PIT.  
P&A COMPLETED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	TITLE	DATE
RAY F. NOKES	PROD. MGR. / ENGINEER.	7/18/96
TYPE OR PRINT NAME	TELEPHONE NO.	
	1-505-623-6601	

(This space for State use)

Approved by: Johnny Robinson Title: \_\_\_\_\_ Date: \_\_\_\_\_

Conditions of approval, if any: \_\_\_\_\_