State of New Mexico

gy, Minerals and Natural Resources Department	
TANKS TO THE COLOR	

OIL CONSERVATION DIVISION P.O. Box 2088 Sonta Fe, New Mexico 87504-2088 Sonta Fe, New Mex	P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Anesis, NM 88210 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ORL WELL ONE P.O. Box 2088 Santa Fe, New Mexico 87504-2088 Sunta Fe, New Mexico 10 10 10 10 10 10 10 10 10 10 10 10 10	30-025-31567 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. V-2258 7. Lease Name or Unit Agreement Name EKay 27 State 8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Fig. Bit Stan, No. No. 18140 P.O. Box 2088 310-025-31567 Statis Dis. Assets Dis. A	P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 DISTRICT.II P.O. Drawer DD, Ariesia, NM 88210 Santa Fe, New Mexico 87504-2088 DISTRICT.III 1000 Rio Brazoi Rd., Ariec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OB. WELL OB. WEL	30-025-31567 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. V-2258 7. Lease Name or Unit Agreement Name EKay 27 State 8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Samia Fe, New Mexico 8/204-2080 S. Indicata Type of Laws	DISTRICT.II P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 875U4-2088 DISTRICT.III 1000 Rio Brazor Rd., Ariec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OR. WELL OTHER WIW 2. Name of Operator Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) 11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	STATE L FEE L 6. State Oil & Gas Lease No. V-2258 7. Lease Name or Unit Agreement Name EKay 27 State 8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "PAPILLATION TO PENMY" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "PAPILLATION TO PENMY" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "PAPILLATION TO PENMY" (FORM C-101) FOR SUCH PROPOSALS TO PRICE OF PENMY" (FORM C-101) FOR SUCH PROPOSALS TO PENMY "PAPILLATION TO PENMY" (FORM C-101) FOR SUCH PROPOSALS TO PENMY "PAPILLATION TO PENMY "PAPILLATI	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ORDER WIW 2. Name of Operator Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) 11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	6. State Oil & Gas Lease No. V-2258 7. Lease Name or Unit Agreement Name EKay 27 State 8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West. Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
SUNDRY NOTICES AND REPORTS ON WELLS (BO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPER OR PLUS BACK TO A (BO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPER OR PLUS BACK TO A (BO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPER OR PLUS BACK TO A (BO NOT USE THIS FORM FOR THE PROPOSALS TO BRILL OR THE PROPOSALS) 1. Type of Well: Wall	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OR. WELL OR. WELL OR. WELL OR. WELL OR. OR. OR. WELL OR. OR. OR. OR. OR. OR. OR. O	EKay 27 State EKay 27 State B. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West. Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
(OO NOT USE THIS FORM FOR PROPERTY OSE SUPPLICATION FOR PERMIT DIFFERENT RESERVORS USE SUPPLICATION FOR PERMIT DIFFERENT RESERVORS USE SUPPLICATION FOR PERMIT DIFFERENT RESERVORS USE SUPPLICATION FOR SUCH PROPOSALS) 1. Type of Well: Nome of Openics	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON THE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ORL WELL OTHER WIW 1. Name of Operator Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	EKay 27 State 8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Use of Start Water of Start Water Start Wa	Name of Operator Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	8. Well No. #1 9. Pool name or Wildcat Undes. Bone Spring 660 Feet From The West Line NMPM Lea County etc.) 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Name of Operator Harvey E. Yates Company 1. Name of Operator Harvey E. Yates Company 1. Address of Operator P.O. BOX 1933, Roswell, N.M. 88202 505/623-6601 Unders Bone Spring 1. Well Locascoe United Enter M: 660 Feet From The South Line and 660 Feet From The West Line Section 27 Township 18S Range 34E NMPM Lea County No. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE ORILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE ORILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER Convert to Water Disposal 12. Describe Proposed or Completed Operations (Clearly state all perioren details, and give perioren dates, including enformed date of sening any proposed world) SEE RULE 1103. 1) Pull production equipment 2) Run plastic coated tbg & nickle coated Baker Loc-set pkr; Set @ 8949¹ 3) Loaded backside Wyker Fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. 1 honory cently that the Informatica above is true and complete to the best of my knowledge and build. 1 theory cently that the Informatica above is true and complete to the best of my knowledge and build. 1 the proof of State Line 2000 S	2. Name of Operator Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) 11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	#1 9. Pool name or Wildcat Undes . Bone Spring 660 Feet From The West Line NMPM Lea County 17 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Harvey E. Yates Company. 1 Address of Operator P.O. Box 1933, Roswell, N.M., 88202 505/623-6601 Undes Bone Spring 1 Well Leater M: 660 Feet From The South Line and 660 Feet From The West. Line Unit Later M: 660 Feet From The South Line and 660 Feet From The West. Line Section 27 Township 18S Range 34E NMPM Lea County 10 Elevation (Naw Worker P.R.R.B., R.G.R. etc.) 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE ORILLING OPNS PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER: OTHER: 12 Describe Proposed or Completed Operations (Clearly state all persisers datails, and give persisens dates, including enhanced date of staning any proposed world) SEE RULE 1103. 1) Pull production equipment 2) Run plastic coated this 8 nickle coated Baker Loc-set pkr; Set 8 8949' 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. 1 India spece for State Use) The Proposed for State Use 11 min. Gum. The Part of Part HAMB. Tim Gum. The Part of P	Harvey E. Yates Company 3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	Undes, Bone Spring 660 Feet From The West Line NMPM Lea County 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
1. Address of Operator P. D. Box 1933, Roswell, N.M. 88202 505/623-6601 Undes Bone Spring P. D. Box 1933, Roswell, N.M. 88202 505/623-6601 Undes Bone Spring 1. Will Location Unit Latter M: 660 Feet From The South Line and 660 Feet From The Nest. Line Section 27 Township 185 Range 34E NMPM Lea County 10. Elevation (Show whether DF, RRB, RF, CR, sec) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CHANGE PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORABILY ABANDON CHANGE PLUG AND ABANDON CHANGE PRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORABILY ABANDON CHANGE PLUG AND ABANDONMENT CASING TEMPORABILY ABANDON CHANGE PRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORABILY ABANDON CHANGE PRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORABILY ABANDON CHANGE PRILLING OPNS. PLUG AND ABANDONMENT CASING THE CONVEY TO Water Disposal 11. Describe Proposed or Completed Operations (Citarly state all periore all deadly, and give periore dates, including stringted date of stating any proposed on the Convey to Water Disposal 11. Pull production equipment 2 Run plastic coated the 8 nickle coated Baker Loc-set pkr; Set @ 8949' 3 Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - OK 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. 1 however sently that the information above in true and complete to the best of my knowledge and belief. 1 however sently that the information above in true and complete to the best of my knowledge and belief. 1 however sently that the information above in true and complete to the best of my knowledge and belief. 1 however sently that the information above in true and complete to the best of my knowledge and belief. 1 however sently that the information above in true and complete to the best of my knowledge and belief. 1 however sently that the information above in true and complete to th	1. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601 4. Well Location Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) 11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	Undes, Bone Spring 660 Feet From The West Line NMPM Lea County 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Weil Location Unit Letter M : 660 Feet from The South Line and 660 Feet from The Mest Line Section 27 Township 18S Range 34E NMPM Lea County 10. Elevation (35now whether DP, RRB, RT, GR, etc.) 4012.7. GL 4012.7. GL NOTICE OF INTENTION TO: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periturnal datally, and give periturnal datas, including snimated data of larning any proposed worth SEE RULE 1103. 13. Pull production equipment 29. Run plastic coated tog & nickle coated Baker Loc-set pkr; Set @ 8949' 30. Loaded backside w/pkr fluid 40. Test backside to 300 psi for 30 min - 0K 50. Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. 1. Note of the backside pressure test is attached. 1. Note of the backside pressure test is attached. 1. MAY 14 1993 MAY 14 1993	Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	NMPM Lea County 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Usit Letter M: 660 Foot From The SQUITH Libos and DBU Feet Hour He Led County Section 27 Township 185 Range 34E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, CR, etc.) 4012.7 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. 12. Describe Proposed or Completed Operations (Clearly state all periorate desir), and give periorate dates, including enimated date of training any proposed world seem of the North Complete on the confidence of the North Complete on the confidence of the North Complete on the test of my bookings and ballet. 1 Pull production education blooms is true and complete to the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete on the test of my bookings and ballet. 1 Indicate Mark Time Gument Complete C	Unit Letter M: 660 Feet From The South Line and Section 27 Township 18S Range 34E Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012.) Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	NMPM Lea County 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Socio 27 Township 18S Range 34E NMPM Lea County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 4012.7 GL	Section 27 Township 18S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, 4012. 11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	NMPM Lea County 7 GL ice, Report, or Other Data SUBSEQUENT REPORT OF:
Interest	Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	ice, Report, or Other Data SUBSEQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	subsequent Report OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: Convert to Water Disposal 12. Describe Proposed or Completed Operations (Clearly state all pertinant datalls, and give pertinant datas, including estimated data of starting any proposed work) SEE RULE 1103. 1) Pull production equipment 2) Run plastic coated thing a nickle coated Baker Loc-set pkr; Set @ 8949¹ 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. Thereby contry that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TIME OF THE DATE OF THE STARLING OF THE PROPERTY OF T	NOTICE OF INTENTION TO:	SUBSEQUENT ALL OUT OF
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: CONVERT to Water Disposal 12. Describe Proposed or Completed Operations (Clearly state all pertinant data), and give pertinant datas, including estimated data of starting any proposed work) SEE RULE 1103. 1) Pull production equipment 2) Run plastic coated the Sanickle coated Baker Loc-set pkr; Set @ 8949' 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. 1. Thereby centry that the information shove is true and complete to the heat of my knowledge and belief. 3. SIGNATURE TIME STARLY BY TIME Engineer 1. DATE 5/7/93 TIME TIME TIME STARLY BY 14 1993 APPROVED BY THE STARLY BY TIME TIME TIME TIME TIME TIME TIME TIME	DEMENIAL WO	
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: CONVERT to Water Disposal ON A STATE WATER D	PLUG AND ARANDON REMEDIAL WC	DK VELETITIES OFFICE
TEMPORARILY ABANDON CHANGE PLANS COMMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: OTHER: Convert to Water Disposal OTHER: Conver	PERFORM REMEDIAL WORK	
OTHER: CASING TEST AND CEMENT JOB CONTROL OF COMPLETE OF STATE AND CEMENT JOB CONTROL OTHER: Convert to Water Disposal OTHER: Convert to Wat	TEMPORARILY ABANDON	TT .
OTHER: CONVert to Water Disposal 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Pull production equipment 2) Run plastic coated the 8 nickle coated Baker Loc-set pkr; Set @ 8949¹ 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. Chart of the backside pressure test is attached. DATE	CASING TEST	
1) Pull production equipment 2) Run plastic coated the senical coated Baker Loc-set pkr; Set @ 8949¹ 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - 0K 5) Start water disposal on 4/30/93 NOTE: Chart of the backside pressure test is attached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Fingineer TITLE TITLE TITLE TITLE TITLE TITLE THE MAY 14 1993 APPROVED BY TITLE TITLE TITLE DATE DATE APPLICATION DATE TITLE DATE		vert to Water Disposal LA
1) Pull production equipment 2) Run plastic coated the solution of the second s	OTHER:	tes, including estimated date of starting any proposed
2) Run plastic coated tbg & nickle coated Baker Located Ba	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give personnel work) SEE RULE 1103.	•
The space for State Use) I hereby certify that the information above is true and complete to the best of my knowledge and belief. The Engineer Date 5/7/93 TELEPHONE NO. 623-660 THE SPACE FOR STATE Use) MAY 14 1993 APPROVED BY DATE DATE	2) Run plastic coated the anickle coated baker to 3) Loaded backside w/pkr fluid 4) Test backside to 300 psi for 30 min - OK 5) Start water disposal on 4/30/93	
(This space for State Use) DEFINE STATE S	to the role and complete to the best of my knowledge and belief.	ineer
APPROVED BY DATE	TYPE OR PRINT NAME TIM GUM	
APPROVED BY		

Jan & Surt 506 par Spring Continue

