

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br><b>30-025-31735</b>   |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>LG7655  |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
Santa Fe Energy Operating Partners, L.P.

3. Address of Operator  
550 W. Texas, Suite 1330, Midland, Texas 79701

4. Well Location  
Unit Letter F : 1980 Feet From The North Line and 1650 Feet From The West Line  
Section 32 Township 18S Range 32E NMPM Lea County

7. Lease Name or Unit Agreement Name  
Watkins "32" State Com

8. Well No.  
1

9. Pool name or Wildcat  
Lusk, N. (Morrow)

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3701.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-7-92: Spud 17-1/2" hole at 5:30 a.m. Drilled to 473'. RU casing crew. Ran 11 jts 13-3/8" 48# H-40 ST&C and set at 473'. Cemented w/ 500 sx C1 "C" + 2% CaCl<sub>2</sub>. Plug down at 10:00 p.m. Circulated 60 sx to pit. WOC.

10-8-92: WOC. Cut casing off and weld on head. NU stack. Repair rotary clutch.

10-9-92: Pick up BHA. Test casing to 600 psi for 30 minutes - okay. Resume drilling operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 10/15/92  
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

OCT 15 1992