Submit 3 Copies to Appropriate District Office

State of New Mexico Ainerals and Natural Resources Department Energ

Form C-103 Revised 1-1-89

FO. Box 1980, 160bbs, NM 88210 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lease STATE IX S. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: "B. OAS 12 ONE 832, Midland, TX 79702 4. Well Location Unit Letter J.: 2310 Feet From The South Line and 1980 Feet From The East Unit Letter J.: 2310 Feet From The Society Mexico (Show whether P. F. R.B. R.T. G. etc.) 10. Elevation (Show whether P. F. R.B. R.T. G. etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ADABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLUG AND ABANDON CHANGE PLANS CHANGE PLUG AND ABANDON	1
Sunday P.D. Artesis, NN 88210 STATE STAT	
SUNDRY NOTICES AND REPORTS ON WELLS COMMENCE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" Type of Well:	FEE
(DO NOT USE THIS FORM FOR PROPOSALS TO SCHILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: OR WELL ON OPERATOR Name of Operator Maralo, Inc. 3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Locations Unit Letter J : 2310 Feet From The South Line and 1980 Feet From The East Section 2 Township 198 Range 32E NMPM Lea 10. Elevation (Show whether DF, RKB, RT, GR. etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND BANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND BANDON CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABAND OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed. Work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light w/94 salt is 1/4# floorele/sx + 200 sx 50/50 poz mx. cent w/, 6% Halad 9 + 3# KCL. int circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and comp	
(DO NOT USE THIS FORM FOR PROPOSALS TO SCHILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: OR WELL ON OPERATOR Name of Operator Maralo, Inc. 3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Locations Unit Letter J : 2310 Feet From The South Line and 1980 Feet From The East Section 2 Township 198 Range 32E NMPM Lea 10. Elevation (Show whether DF, RKB, RT, GR. etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND BANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND BANDON CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABAND OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed. Work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light w/94 salt is 1/4# floorele/sx + 200 sx 50/50 poz mx. cent w/, 6% Halad 9 + 3# KCL. int circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 hereby certify that the information above is true and comp	
Type of Well: ONE ONE OTHER	
1. Type of Well: Some of Operator Will Some of Operator Warralo, Inc. 2. Name of Operator Marralo, Inc. 3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Location Unit Letter J: 2310 Feet From The South Line and 1980 Feet From The Eas Section 2 Township 198 Range 32E NMPM Lea MARD Section 2 Township 198 Range 32E NMPM Lea NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON CHER: OTHER: OT	
ONLINE 2. Name of Operator Maralo, Inc. 3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Location Unit Letter J.: 2310 Peet From The South Line and 1980 Peet From The Eas Section 2 Township 198 Range 32E NMPM Lea 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDO PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed on the state of the stat	9
2 Name of Operator Maralo, Inc. 3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Losin J. 2310 Unit Letter J. 2310 Feet From The South 198 Range 32E NMFM Lea 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB CASING CHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with two proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with SEE RULE 110310-92 Spud @ 4:30 AM -11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 1-1/4". WOC 15 hrs19-92 Ran 88 jst. 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. ALL WORLD AND AND AND AND AND AND AND AND AND AN	
3. Address of Operator P. O. Box 832, Midland, TX 79702 4. Well Location Unit Letter J: 2310 Feet From The 19S Range Section 2 Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemented w/700 sx Howco Light of Completed Systems of Society State all pertinent dates in Completed W/700 sx Howco Light of Complete Systems of Society State Society Societ	
P. O. Box 832, Midland, TX 79702 4. Well Location Unit Letter 2: 2310 Feet From The South 19S Range 32E NMFM Lea 19S Range 32E NMFM Lea 19S Range 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed. work) SEE RULE 1103. -10-92 Spud @ 4:30 AM -11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cernt circ to surface. Hole size 2-1/4". WOC 15 hrs. -19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented W/700 sx Howco Light to surface. Hole size 3-1/4# flocele/sx + 200 sx 50/50 poz mx. cernt W/.6% Halad 9 + 3# KCL. The circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Intervity certify that the information above is true and complete to the best of my knowledge and belief. The POWNER OF NAME AND ADD TEST PARTY. THE PREMENCE.	
Unit Letter J 2310 Feet From The South Line and 1980 Feet From The East Section 2 Township 198 Range 32E NMPM Lea 1980	
Section 2 Township 19S Range 32E NMPM Lea 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDO PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cent circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cent w/.6% Halad 9 + 3# KCL. Int circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 31d @ 3675'. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Data Chapter TITLE Agent TITLE Agent TITLE Agent TITLE TERPHONENO.	t Line
Section Township Range NMPM 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687.5 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK	Line
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDO PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent data)s, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cent circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cent w/.6% Halad 9 + 3# KCL. Int circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Agent The Data Characters of the part of the	County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABAND CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Describes Queens TILE PROPERSON.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABAND CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light to W/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. DIUG AND ABAND CASING TEST AND CEMENT JOB CASING TEST AND	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. DELIGIOR AND ABAND PULL OR ALTER CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. TEST AND CEMENT JOB CASING TEST AND	
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Describes Outens.	
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Agent DATE TILE Agent TILE PHONE NO.	ONMEN I L
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. 1hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Described Outputs THE PHONE NO. (TELEPHONE NO.)	
Work) SEE RULE 1103. 1-10-92 Spud @ 4:30 AM 1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Darithus Queens TILE Agent DATE DOTOT best Queens TILE PRIONE NO. (TELEPHONE NO.)	
1-11-92 Ran 11 jts. 8-5/8" 24# J-55 csg. Set @ 462'. Cemt circ to surface. Hole size 2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Descriptions. Our Description of the complete to the best of my knowledge and belief. Descriptions Our Descriptions. TILE Agent TILE Agent THE PROPERSON.	!
2-1/4". WOC 15 hrs. 1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Describes Owens. THE PRINCE NO. (TIPLE PRONE NO. (TELEPHONE	.
1-19-92 Ran 88 jst 5-1/2" 15.5# & 17# csg. Set @ 3675'. Cemented w/700 sx Howco Light mt w/9# salt & 1/4# flocele/sx + 200 sx 50/50 poz mx. cemt w/.6% Halad 9 + 3# KCL. mt circ to surface. Hole size 7-7/8". WOC 15+ hrs. Tested to 1000 psi - ok. d'd @ 3675'. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Description. Time Agent Descriptions Of the process. Telephone No. (Income and Complete to the best of my knowledge and belief.) Descriptions Of the process. The page 12-9-15 page 12-9-	•
Thereby certify that the information above is true and complete to the best of my knowledge and belief. Signature Darsthan Owens The Private of the control of the c	ıt
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Described To 1000 psi - OK. WOC 15+ hrs. Tested to 1000 psi - OK. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Described Outens. THE PRINTERNO. (TELEPHONE NO. (
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DENOTE: DON'T THE AGENT DATE DON'T THE THORNE NO. (
SIGNATURE SIGNATURE Agent DATE TELEPHONE NO. (
SIGNATURE STATE OLIVERS TITLE Agent DATE TELEPHONE NO. (
SIGNATURE STATE OLIVERS TITLE Agent DATE TELEPHONE NO. (
SIGNATURE SIGNATURE Agent DATE TELEPHONE NO. (
SIGNATURE DATE TILLE Agent DATE TELEPHONE NO. (
SIGNATURE DON'T THE Agent DATE TELEPHONE NO. (
SIGNATURE DATE TILLE Agent DATE TELEPHONE NO. (
Dorothoa Owens TELEPHONE NO. (-92
	915)684-
(This space for State Use)	
Ong, Signed by	
Paul Kantz APPROVED BY Geologist TITLE DATE	1 1 '9'