

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002531876
5. Indicate Type of Lease	STATE ☐ FEE ☐
6. State Oil / Gas Lease No.	B-1733-2
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	121
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3986', KB-4000'	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>A</u> : <u>964</u> Feet From The <u>NORT</u> Line and <u>90</u> Feet From The <u>EAST</u> Line Section <u>1</u> Township <u>18-SO</u> Range <u>34-EA</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☒ ALTERING CASING ☐ COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: Squeeze off perms & reperf & Acidize ☒
--	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-26-99: MIRU. WELL SI ON VAC. NDWH. NUBOP.
 5-27-99: UNLOAD & RACK WS. FULL OF SAND. REL PKR. TIH W/BIT & BAILER ON WS. STOP BIT @ 5810'.
 5-28-99: TIH TO 6020-TAG & CLEAN OUT FR 6020-6152'. PLUGD BAILER. TIH W/BIT & SAME BAILER ON WS. C/O 6152-6280'. C/O SCALE FR BAILER.
 5-29-99: TIH W/CMT RET ON WS TO 5862'. PUP THRU RET & SET @ 5862'. PRESS CSG TO 500#-OK. SQUEEZE GLORIETA CSG PERFS 5996-6238' W/100 SX CL C W/3% D156. TAIL IN W/100 SX CL C NEAT. STING OUT OF RET. DUMP 1 BBL CMT ON TOP OF RET.
 6-01-99: TIH W/BIT, DC'S, & TBG. TAG @ 5806'. DRILL CMT 5806-5862'. DRILL RET @ 5862'. DRILL CMT TO 5908'. CIRC CLN.
 6-02-99: DRILL CMT 5980-6000'. DRILL CMT STRINGERS TO 6074'. TAG SOLID. CIRC CLN. RAN GR/CCL FR 6067-4850'. CORRELATE & PERF 5998-6020, 6028-6044. TIH W/PKR TO 932'.
 6-03-99: TIH & SET PKR @ 5866'. PSI CSG TO 500-OK. ACIDIZE W/2500 GALS 15% NEFE & 500# RK SLT. RU SWAB. END FL @ 1200'. REL PKR.
 6-04-99: CHANGE RAMS IN BOP. TIH W/PKR, TBG. NDBOP. NUWH. CIRC PKR FLUID. SET PKR @ 5911'. PSI CSG TO 500-OK. CHART FOR NMOC. RETURN TO WIW.
 6-11-99: ON 24 HR INJ. INJ'G 2383 BWPD @ 0 PSI.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>J. Denise Leake</u>	TITLE <u>Engineering Assistant</u>	DATE <u>6/16/99</u>
TYPE OR PRINT NAME <u>J. Denise Leake</u>	Telephone No. <u>397-0405</u>	
ORIGINAL SIGNED BY <u>GARY W. WINK</u> APPROVED BY <u>FIELD REP. II</u> TITLE <u>FIELD REPRESENTATIVE</u> DATE <u>6-28-99</u> CONDITIONS OF APPROVAL, IF ANY:		

JC9

