

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-31891

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒

GAS WELL ☐

OTHER

2. Name of Operator
Rand Oil & Gas, Inc.

8. Well No.
1

3. Address of Operator
4006 Beltline Road, Suite 290, Addison, Texas 75244

9. Pool name or Wildcat
wildcat

4. Well Location

Unit Letter 0 : 400 Feet From The south Line and 2242 Feet From The east Line

Section 1 Township 18-S Range 38-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3656.7 gr

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work to commence 30 August 1993 / 8-5/8" is cemented to surface. 4 1/2" top of cement is 3,695'. Cut off 4 1/2" at 3690 and pull casing.

Procedure for plugging:

- Set bridge plug between 5,000 and 6,000 ft. Dump 35' or 25sx of cement.
- Set cast iron bridge plug at 4075 ft and dump 35' or pump 25 sx of cement.
- Set stub plug at 3690 ft; 50 ft in and 50 ft out of stub. Wait a few hours and tag plug.
- Set stub plug at 8-5/8" shoe, 50 ft in and 50 ft out and also tag.
- At 350 ft, dump (whichever is greater) 100 ft or 25 sx
- 10 sx surface plug

Between plugs, 10# brine with 25# gel per barrel

OCD will be notified 24 hours prior to plugging.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jan A. DeVault TITLE agent

DATE 10 August 1993

TYPE OR PRINT NAME Jan A. DeVault

(915) 694-6059

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____

DATE AUG 17 1993

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103