

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-31954
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. Fee lease
7. Lease Name or Unit Agreement Name: EKAY 28 STATE
8. Well No. 3
9. Pool name or Wildcat DIOS MANO DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Harvey E. Yates Company

3. Address of Operator
P.O. Box 1933, Roswell, New Mexico 88202

4. Well Location

Unit Letter O : 990 feet from the SOUTH line and 1650 feet from the EAST line

Section 28 Township 18 S Range 34 E NMPM County LEA

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4019.8' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ADD PERFORATIONS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

2/22/03 MI RU SMITH & MARRS. POOH LAYING DOWN 195 3/4" RODS. SI, SDFWE.
2/25/03 POOH W/150 JTS 2 3/8" TBG. RU WIRELINE TRUCK AND GIH W/5 1/2" CIBP & SET AT 4800' WITH 35' CEMENT ON TOP. GIH W/2 3/8" TBG & CIRC CSG W/9# MUD. PULLED UP TO 3600' AND SPOT 35 SX CEMENT (TAG UP AT 3360'). PULL UP TO 1830', SPOT 35 SX CEMENT. PULL TBG UP HOLE.
2/26/03 WELD ON CASING STUB ONTO 5 1/2" CSG. GIH & CUT CSG OFF @ 632'. POOH LAYING DOWN 14 JTS 5 1/2" CSG. GIH W/2 3/8" TBG TO 680' AND SPOT 70 SX CEMENT. TAG UP @ 414'. SPOT 15 SX CEMENT FOR SURFACE PLUG. SDFN.
2/27/03 INSTALL DRY HOLE MARKER, CLEAN LOCATION & RIG DOWN.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 2/28/03

Type or print name Jeanetta Atkinson

Telephone No. 505-623-6601

(This space for State use)

APPROVED AND SIGNED BY COPIES TO WINK TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE
Conditions of Approval: If any: