

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	
3002531991	
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE
6. State Oil / Gas Lease No.	B-1031
7. Lease Name or Unit Agreement Name	
NEW MEXICO -AB- STATE	
8. Well No.	10
9. Pool Name or Wildcat	
VACUUM DRINKARD	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.									
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER								
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.								
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702								
4. Well Location									
Unit Letter	J	2310	Feet From The	SOUTH	Line and	2110	Feet From The	EAST	Line
Section	6	Township	18-SO	Range	35-EA	NMPM	LEA	COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		GR-3975', KB-3989'							

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	TA WELL <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-25-01: MIRU. LD RDS & PMP.
7-26-01: INSTL BOP. ATTEMPT TO REL TA. WORK STUCK TBG. PUMP 70 BFW. WORK STUCK TBG.
7-27-01: RU WL. RAN FREE POINT. STUCK @ 7690'. CHEMICAL CUT 2.875" TBG @ 7665'. RIG DOWN WL.
7-30-01: TIOH W/OVERSHOT & JARS. LATCH ONTO FSH. JAR 3.5 HRS. FISH CAME LOOSE.
7-31-01: TIH W/BIT & BAILER. TAG @ 7730'. FELL THROUGH TO 7745'.
8-01-01: TIH W/PKR & SET @ 7515'. TEST TO 500-OK. RU & SWAB. FL @ 2000. END FL @ 4200.
8-02-01: TAG FLUID @ 2000. REL PKR. PKR SWINGING @ 1800'.
8-03-01: TIH W/CSG SCRAPER TO 7580'. TIH & SET CIBP @ 7550'.
8-06-01: CIRC TRTD WTR. CHART CSG TO 500 PSI-OK. CHART ATTACHED.
8-07-01: RIG DOWN.

WELL IS TEMPORARILY ABANDONED.

This Approval of Temporary
Abandonment Expires 8/24/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE J. Denise Leake TITLE Engineering Assistant

TYPE OR PRINT NAME J. Denise Leake

DATE 8/15/01

Telephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

