

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL & GAS COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Dry Hole - Plugged and Abandoned

2. Name of Operator
Santa Fe Energy Operating Partners, L.P.

3. Address and Telephone No.
550 W. Texas, Suite 1330, Midland, Texas 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
(N), 660' FSL and 1980' FWL, Sec. 29, T-18S, R-32E

5. Lease Designation and Serial No.

NM-77052

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Watkins 29 Federal #1

9. API Well No.

30-025-32177

10. Field and Pool, or Exploratory Area

North Lusk (Bone Spring)

11. County or Parish, State

Lea Co., NM

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/20/93: MIRU. Blew well down to test tank. ND wellhead. NU BOP. Released Uni VI packer. POOH w/ 88 jts 2-3/8" tubing and BHA. RIH w/ tbg. Set CIBP at 3050'. Mix 10# mud, displaced hole w/ mud. Spot 35 sx Cl "C" cement on top of CIBP. POH and lay down 10 jts tubing. EOT at 2735'. Spot 30 sx Cl "C" cmt. POH w/ 48 stands.

12/21/93: ND BOP. Free point csg at 1517'. RIH w/ csg cutter and cut off 5-1/2" at 1520'. POOH w/ 34 jts 5-1/2" J-55 casing and 2 - 14' cut off joints. NU BOP. RIH w/ 48 jts 2-3/8" tubing to 1580'. Spot 30 sx Cl "C" cmt. POOH w/ tbg and SDFN to WOC.

12/22/93: RIH w/ tubing and tag plug at 1424'. POH w/ tbg to 510'. Spot 30 sx Cl "C" (BLM have approval not to tag plug at 510'). POH w/ tbg to 50' and spot 10 sx surface plug. RDP. Cut wellhead off 3' below ground level and installed dry hole marker w/ legals. Dug up dead men, clean location. Well plugged and abandoned.

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Production Clerk

Date Dec. 28, 1993

(This space for Federal or State office use)

Approved by Orin, Signed by Adam Salameh
Conditions of approval, if any:

Title Petroleum Engineer

Date 1/21/94