

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 801

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

WYATT PHILLIPS FED #15

9. API Well No.

30-025-32417

10. Field and Pool, or Exploratory Area

MALJAMAR

11. County or Parish, State

LEA COUNTY, NM

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SOUTHWEST ROYALTIES, INC.

3. Address and Telephone No.

P.O. BOX 11390, MIDLAND, TX 79702 (915) 686-9927

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 990' FWL

SEC. 34, T-17S, R-33E

2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other PERF, ACIDIZE & FRAC
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-5-94 RU WEDGE WL; RAN CIBP ON WL, SET PKR AT 4550'; PERF GRAYBURG ZONE AT 4443', 4445', 4447', 4449', 4451', 4453', 4455', 4457', 4459', 4461', 4463', 4465', 4473', 4475', 4477', 4479', 4481', 4483', 4485', 4487' & 4489' (21 HOLES) TESTED CIBP TO 2000# -OK.

7-6-94 SPOT 200 GALS 7 1/2% NEFE ACID; TST TO 500# - OK; ACIDIZE GRAYBURG 4443' - 4489' with 2000 GALS 7 1/2% NEFE; FLUSHED WITH 2% KCL WATER.

7-12-94 FRAC GRAYBURG PERFS 4443' - 4489' WITH 18,000 GALS BORATE 330 GEL WITH 40,000# 20/40 OTTOWA SD AND 16,000# 20/40 RC SD; FLUSHED WITH SLICK GEL.

9 99A

SJS

14. I hereby certify that the foregoing is true and correct

Signed Kate E. Olson

Title REGULATORY ASST.

Date 7-14-94

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____