Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

. W. OIL CONS. COMMISSION BOX 1980 HORBS NEW MEXICO 88240

NM-59045

-	uuget bute	eau No. I	304-0135
	Expires:	March 31	, 1 99 3

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to deepen or reentry to a different re	servoir.
Use "APPLICATION FOR PERMIT" for such proposals	AND DESCRIPTION OF THE PARTY OF

Use "APPLICATION	FOR PERMIT" for such proposal	S	6. If Indian, Alotte	e or Tribe Name	
SUBM	IIT IN TRIPLICATE	A CHIEN	A If Unit or CA, A	greement Designation	
I. Type of Well: OIL GAS WELL WELL	⊠ OTHER P&A		8. Well Name an	d Number EDERAL (USA) 'J'	
2. Name of Operator TEXACO EXPLOR.	ATION & PRODUCTION INC.	3012		5	
Address and Telephone No. P.O. Box 46510, De	enver Colorado 80201-6510	(303)621-485	9. API Well No.	30-025-32449	
4. Location of Well (Footage, Sec., T., R., M., or Survey Unit Letter O : 999 Feet From TI	Description) /6531	Feet From The	10. Field and Poo	ol, Exploratory Area RE, WEST	
EAST Line Section 30	Township 19-S Rang	e 32-E	11. County or Pai	rish, State LEA ,NM	
2. Check Appropriate	Box(s) To Indicate Natu	re of Notice, Re	port, or Oth	er Data	
TYPE OF SUBMISSION	:	TY	PE OF ACTION	2 2	
Notice of Intent	Abandonment Recompletion Plugging Back			Change of Plans New Construction Non-Routine Fracturing	11
Subsequent Report Final Abandonment Notice	☐ Casing Repair ☐ Altering Casing ☐ OTHER:	COMPLETION		Water Shut-Off Conversion to Injection Dispose Water	į.
		3333 2211011		ete: Report results of multiple completion on hopetion or Recompletion Report and Log Fo	

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*.
- 1. MIRU POOL UNIT. RU WEDGE WLU. PERF'D W/ 2 JSPF: 6908-6924'. 32 HOLES. STARTED TIH W/ PKR AND 2-7/8" TBG. 09-19-95.
- 2. FINISHED TIH. PKR SET @ 6803'. 09-20-95. UNSET PKR AND RAN THRU PERFS. RESET PKR. 09-22-95.
- 3. REL PKR. TOH. LD TBG. 09-23-95.
- RU WEDGE AND SET CIBP @ 6890'. DUMP 35' CMT ON PLUG. PERF'D W/ 2 JSPF: 6680-6686'. 12 HOLES. 09-24-95.
- RU DOWELL. DOWELL ACIDIZED W/ 2,000 GALS 7-1/2% NEFE. DOWELL FRAC'D W/ 15,000 GALS 30# XLG KCL AND 58,000# 16/30 OTTOWA DOWN CSG. 09-27-95.
- RU WEDGE. SET RBP @ 6568'. RU DS. TEST RBP TO 4500#. DUMP 10' SAND ON RBP. PERF'D W/ 2 JSPF: 6520-6530'. 09-29-95.
- TIH W/ NC, TBG TO 6550'. 09-30-95.
- DOWELL ACIDIZED W/ 2000 GALS 7-1/2% HCL. RD DS. TOH. LD TBG. 09-30-95.
- DOWELL FRAC'D W/ 15,000 GALS 30# XLG KCL AND 58,000# 16/30 OTTOWA SAND. 10-02-95.
- 10. ND FRAC VALVE, BOP, TBG HD. NU 3000#. WELL HD, BOP. TIH W/ RETRIEVING TOOL ON TBG. REL RBP. TOH. LD RBP. TIH W/ NC ON TBG TO 5000'. 10-04-95.
- 11. TIH W/ PROD TBG, MA-PS-SN-6 JTS-TAC-212 JTS 2 7/8" TBG, SN @ 6705'. ND BOP. RUN 2-1/2" X 1-3/4" X 24 PUMP. 10-05-95.
- 12. HOOK UP FLOWLINE. START WELL PUMPING. 10-06-95.
- 13. RU POOL WELL SERV. PULL PUMP AND RODS. START TOH W/ TBG. 10-21-95.
- 14. SET CIBP 2 6450'. DUMP BAIL 35' CMT ON CIBP. PERF'D W/ 2 JSPF: 5328-5352', 5368-5388'. 88 HOLES. 10-24-95.
- 15. RU DOWELL. ACIDIZED W/ 2500 GALS 7-1/2% NEFE. 10-24-95.
- 16. TIH W/ RODS. TOH. LD RODS. TOH W/ TBG. RU WEDGE. SET CIBP @ 5275'. DUMP 35' CMT. PBTD 5240'. 10-29-95.
- 17. PREP TO P&A. FROM DRLG TO P&A 11-01-95.

- un representative	TITLE Drilling Operations Mgr.	DATE 11/8/95
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE J. Ja X
	on knowingly and willfully to make to any department or agency of the United States a	any false, fictitious or fraudulent statements or

