Submit 3 Copies to Appropriate District Office

State of New Mexico Energy inerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM \$8240

OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206

W	LL API NO.
L	30-025-325
	Indiana Toma of Lase

DISTRICT II	30-025-32538				
P.O. Drawer DD, Artesia, NM \$8210	5. Indicate Type of Lease				
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410	STATE FEE				
	6. State Oil & Gas Lease No. VA-473				
SUNDRY NOTI	CES AND REPORTS ON WEI	LLS			
(DO NOT USE THIS FORM FOR PRO	7. Lease Name or Unit Agreement Name				
	IVOIR. USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	RMIT	· · · · · · · · · · · · · · · · · · ·		
1. Type of Well:	101,1010011110100201,		4		
OIL GAS WELL	OTHER		La Rica "32" State		
2. Name of Operator		-	8. Well No.		
Mewbourne Oil Company			1		
3. Address of Operator	In. Marian 00241		9. Pool name or Wildcat		
P.O. Box 5270 Hobbs, N	iew Mex1co 88241	- ·	E-K Bone Spring		
) South	1980	Nos+		
Unit Letter K :_ 1300	Feet From The 300 cm	Line and	Feet From The West L		
Section 32	Towaship 18S R	ange 34E	NMPM Lea County		
	10. Elevation (Show whether	—p-	NMPM Lea County		
	3879' GR	·			
11. Check A	ppropriate Box to Indicate 1	Nature of Notice, Re	eport, or Other Data		
NOTICE OF INTE	ENTION TO:	_	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	OLUGAND ADARDON				
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB		
OTHER.	الحيا	•			
OTHER:		OTHER:			
12. Describe Proposed or Completed Operation	ons (Clearly state all pertinent details, a	und give pertinent dates, inclu	iding estimated date of starting any proposed		
work) SEE RULE 1103.					
Mewbourne Oil proposes	to plug and abandon	the La Rica "32'	'State #1 as follows:		
	or pray and abandon	0,10 22 11,102 32	5 00 0C 11 03 10 10 10 15.		
1. Set a CIBP @ 9,000	' and cap with 35' ce	ment.			
2. Set 20 sk. cement	plugs @ 5260' and 325	0'.			
3 Cut ass 5 1/21 and	n= 0 24001	1 A 2250	N 24501		
3. Cut off 5-1/2" casi	ng @ 2400°. Set a ce	ment plug @ 2350	<i>1</i> - 2450 .		
4. Set a cement plug @	357' - 457'				
See a cement prag e	307 137 .				
5. Set a 10 sk. cement	plug @ surface.				
	. .				
I hereby certify that the information about is true and	complete to the heat of my knowledge and hel-	ief.			
SCINATION LONG MAN			ger Dec. 8, 1994		
SKINATURE		บาวนานนานแส	.uci		

I hereby certify that the info	rmation about is true and complete	to the best of my knowledge and belief.				
SIGNATURE	lythy	me	District Manager	DAT	Dec. 8,	1994
TYPE OR PRINT NAME	Kelly Ryan	·	TELEPHONE NO.	(505)	393-5905	
(This space for State Use)		H CHIMION			0E8 1 8	1004
APTROVED BY		₩		DAT		