Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re			Form C-103 Revised 1-1-89
DISTRICT I P.O. Bax 1980, Habbs, NM 88240	OIL CONSERVATIO		WELL API NO.	
DISTRICT II	P.O. Box 208		30-025-3272	1
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		· .	6. State Oil & Gas Lease I K-4606	
( DO NOT USE THIS FORM FOR PRO DIFFERENT RESEN	ICES AND REPORTS ON WEL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEI -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Ag	reement Name
1. Type of Well: OL GAS WELL X WELL	OTHER	······································	NORTH VACU	UM ABO NORTH
2 Name of Operator SAGE ENERGY COMPAN	Y		8. Well No. 73	
3. Address of Operator			9. Pool name or Wildcat	
PO DRAWER 3068	Midland, Texas 7	9702	NORTH VACUU	M ABO
	0 Feet From The NORTH	Line and 19	80 Feet From The	EAST Line
Section 1	170	245	NMPM Lea	
	10. Elevation (Show whether ) 4029 GR	41 E C		
11. · Check	Appropriate Box to Indicate N	Nature of Notice, R	eport, or Other Data	
NOTICE OF INT			SEQUENT REPO	
		REMEDIAL WORK	ALTER	
PULL OR ALTER CASING		CASING TEST AND CE		
OTHER:		OTHER:	·	
<ol> <li>Describe Proposed or Completed Opera work) SEE RULE 1103.</li> </ol>		l d give pertinent dates, inclu	ding estimated date of starting	ату proposed
PRODUCTION CASIN (SEE ATTACHED PA				
I hereby certify that the information above is true	and complete to the best of my knowledge and i			******
SIGNATURE COLLIC	/ 0	Production		
TONYA S	treun	·		15) ерноне но. — 683—527
Chis space for State Strife GINAL SIGNED	BY JURRY SEXTON SUMERVISOR			DEC 1 4 1994
	рано - 1975 - 1976 желан 	_		

CONDITIONS OF	APPROVAL,	*	ANY:

-

1394

OFFICE

## SAGE ENERGY COMPANY

## NVANU #73 PRODUCTION CASING

## NVANU "7-C" #3 - NORTON DRILLING - NOVEMBER 20, 1994

KB: 14' 13-3/8" Casing set at 400' KB (17-1/2" hole, circulate cement) 8-5/8" Casing set at 4610' KB (11" hole, circulate cement) Hole Size: 7-7/8" TD: 8860' KB Drilled to TD, circulate, POH and laid down to run casing as follows: 1 Weatherford Float Shoe 1.40' 1 Jt. 4-1/2" N-80 11.6# LT&C Casing (Shoe Jt) 32.781 1 Weatherford Float Collar 1.40' 5 Jts. 4-1/2" N-80 11.6# LT&C Casing 214.61' Jt. 4-1/2" N-80 11.6# LT&C Casing (Marker Jt) 1 33.55' Jts. 4-1/2" N-80 11.6# LT&C Casing 304.04' 7 36 Jts. 4-1/2" J-55 11.6# LT&C Casing 1550.08' 21 Jts. 4-1/2" J-55 10.5# ST&C Casing 902.09' 1 Weatherford DV Tool 2.31' 87 Jts. 4-1/2" J-55 10.5# ST&C Casing 3726.72' 49 Jts. 4-1/2" J-55 11.6# LT&C Casing 2112.84' 207 Jts. 4-1/2" Casing 8881.82' 4-1/2" Casing above KB 21.82' 8860.00' KB 4-1/2" Casing set at

PBTD at 8824.42' KB

DV Tool at 5817.74' KB

RU BJ Services to cement as follows: (1st stage - Float Shoe and 10 Centralizers) Lead with 500 gals Mud Clean, pump 350 sxs Class "C" cement with 2% Gel, 3 pps KCL, 1/4 pps Celoflake and 4% FL-25, flush with 47 bbls water and 92 bbls mud. Plug down at 2:50 AM (11-21-94) Open DV Tool and circulate 3 hours. (2nd Stage - DV Tool and 2 Centralizers) Pump 500 gals Mud Clean and lead with 100 sxs Class "C" Lite, tail in with 250 sxs Class "C" cement with 2% A-7P and 1/4 pps Celoflake, flush with 92 bbls water. Plug down at 7:10 AM (11-21-94). Casing Reciprocated thru 1st stage only. Nipple down and set slips, released rig. TOC at 3875' by Temperature Survey.