

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32802
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1306
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	195
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3976' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>A</u> : <u>729</u> Feet From The <u>NORTH</u> Line and <u>1313</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3976' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ C/O, PERF/STIMULATE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-30-00: MIRU. UNSEAT PUMP. NDWH. NUBOP REL TAC. TIH W/BIT. PU WS. STOP BIT @ 1680'.  
5-31-00: TAG @ 4764'. C/O TO 4772'.  
6-01-00: TIH W/LOG TOOL. RUN GR/CCL 4798-3798'. TIH W/PERF GUN. PERF IN VGSA FORM 4718-4738. TIH W/PKR, SN, TBG. PSA 4202'.  
LOAD/PSI CSG TO 500-OK.  
6-02-00: ACIDIZE VGSA PERFS 4268-4738 W/12,000 GALS 20% NEFE & 6000# RK SLT.  
6-05-00: FL @ 850'. END 3000'.  
6-06-00: REL PKR. TIH W/BIT. TAG @ 4744'. C/O SALT FILL 4744-4772'. TIH W/PROD TBG STOP @ 2394'.  
6-07-00: NDBOP. SET TAC. LAND TBG. NUWH. SN @ 4706'. TAC @ 4036'. TIH W/STRAINER NIPPLE, PUMP, RDS. PLACE WELL ON PUMP.  
6-08-00: RIG DOWN.  
6-23-00: ON 24 HR OPT; PUMPED 153 BO, 369 BW, & 33 MCF.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/26/00  
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_