

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-32810

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

B-1306

7. Lease Name or Unit Agreement Name

CENTRAL VACUUM UNIT

8. Well No.

244

9. Pool Name or Wildcat

VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL ☐ GAS ☐ OTHER ☐ INJECTION

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter B : 10 Feet From The NORTH Line and 1930 Feet From The EAST Line

Section 6 Township 18-S Range 35-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3973' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒ ADD PERFS, STIMULATE, RUN CO-2 EQPT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-08-00: MIRU. NDWH. NUBOP. REL PKR. TIH W/SAFETY COLLAR, PU TBG. SCREW ONTO PKR @ 4355'. REL SAME. TIH W/BIT, DC'S & 2 7/8" TBG. STOP BIT @ 4211'.

2-09-00: LOWER BIT. TAG @ 4370'. C/O SCALE.

2-10-00: TIH W/PERF GUN, PERF VGSAU FORM 4680-4700. TIH W/PKR, SN & TBG. PSA 4212'. PSI CSG TO 500-OK.

2-11-00: ACIDIZE PERFS 4275-4700 W/12,000 GALS 20% NEFE HCL & 6000# RK SLT. FLOW WELL TO TANK.

2-14-00: REL PKR. TIH W/BIT, & TBG. TAG SALT FILL @ 4680'. C/O TO 4783'.

2-15-00: TIH W/PUMP OUT PLUG, PKR, ON/OFF TOOL & TBG.

2-16-00: PSA 4236'. REL ON/OFF TOOL. NDBOP. NU CO-2 TREE, TEST PKR TO 500 PSI. CHART FOR 30 MIN FOR NMOC-D-OK. CIW TEST WELLHEAD TO 3000 -PSI. SHEAR PUMP OUT PLUG @ 2400 PSI. RIG DOWN.

3-08-00: ON 24 HR INJ. INJ'G 1869 BWPD @ 1646 PSI.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE Engineering Assistant

DATE 4/12/00

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JCS

