

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOC - HOBBS

FORM APPROVED
Budget Bureau No. 1804-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE
BUREAU OF LAND MGMT
HOBBS, NM

Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

Name of Operator
BASIN OPERATING CO.

Address and Telephone No
635 PETROLEUM BLDG.

Location of Well (Footage, Sec., T., R., M., or Survey Description)
ROSWELL NM 88201

5. Lease Designation and Serial No.

LC 069276

6. If Indian, Allottee or Tribe Name:

7. If Unit or CA, Agreement Designation

L

8. Well Name and No

HUDSON FED "31"

9. API Well No

2

10. Field and Tract, or Exploratory Area

CORBIN BONE SPRING SOL

11. County or Parish, State

LEA, N.M.

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set CIBP at 9800 to abandon production from 9938 to 10065. Perforate 4 holes each at 8900 and 8725 Feet. Pressure up to 2000#. Spot 40 sx Class H cmt from 8900 to 8701. Reverse out 6 Barrells cmt to surface. Perforate First bone Spring from 8660-70 with 20 holes. Acidize with 1000 gals 7.5% NeFe. Frac with 7000 gals 35# XL-gel pad + 17250 gal 35# X-L gel carrying 37500# 20-40 sd + 37500# 20-40 RC. Perforate 7426-7432, 14 holes, A/1000, Frac 11250 gals + 30000# sand. Recovered load + 100 BWPD with 1% oil cut from 7426-8670. Set CIBP at 7400' + dumped 35' cement on top. Perforate Delaware 5994-6000 A/500 7.5% NeFe, Frac with 5000 gals + 10500# sd. Recovered load + 100% salt waters. Set CIBP at 5400'. Dumped 35' cement on top of CIBP. Perforate Queen at 4134-36, 4142-44 with 4 spf. A/1000 gals. Swabbed 100% saltwater. Plan to Plug and Abandon.

14. I hereby certify that the foregoing is true and correct.

Signed

Title

Date

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

ACCEPTED FOR RECORD

AUG 20 1996

BLM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side