N.M. OIL CONS. COMMISSION P.O----OX 1980 HObus, NEW MEXICO 88240

Form 3160-5 June 1990)		ED STATES [OF THE INTERIOR		FORM APPROVED Budget Bureau No. 1004-013 Expires: March 31, 1993		
	BUREAU OF L	AND MANAGEMENT	1	ase Designation and Serial No	•	
Do nol use	this form for proposals to dril	AND REPORTS ON WELLS I or to deepen or reentry to a different reserve PERMIT—" for such proposals	6. 11	C 069276 Indian, Allottee or Tribe Nam	e	
		IN TRIPLICATE	7. 17	Unit or CA. Agreement Desig	nation	
1. Type of Well				Il Name and No.		
Oil Gas Well Well Outer			Hu	Hudson Federal "31"		
2. Name of Opera			9. AP	I Well No.		
Robert N	. Enfield			2	Area	
3. Address and Telephone No. P. O. Box 2431, Santa Fe, New Mexico 87501 (505) 988-2863				10. Field and Foot, pr Epploratory Area		
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description)			11. C	Indepignated S Corbin		
990' 010D FNL	& 790' FWL of Sec. 31,	т-18-5, к-33-е		Lea		
12. Cł	IECK APPROPRIATE BOX(B) TO INDICATE NATURE OF NOTICE, RE	PORT, O	R OTHER DATA		
	PE OF SUBMISSION	TYPE OF ACT	ION			
<u> </u>		Abandonment		Change of Plans		
	Notice of Intent	Recompletion	ـــــــــــــــــــــــــــــــــــــ	New Construction Non-Routine Fracturing		
<u>x</u>	Subsequent Report	Plugging Dack	Ē	Water Shut-Off		
نين ا	-	Casing Repair		Conversion to Injection		
	Final Abandonment Notice		aning	Dispose Water		
L		X Other Spud and surface of			ction on Well	
		installation.	100	nic: Report results of multiple completion ar Recompletion Report an	a rol tourn	
· : :		installation.	100	nic: Report results of multiple completion ar Recompletion Report an	a rolliount	
13. Describe Prep give subs	nosed or Completed Operations (Clearly state al surface locations and measured and true vertice Spudded Conductor hol	Installation. I pertiment details, and give pertiment dates, including estimated date of al depths for all markers and zones pertiment to this work.)* C.	100	nic: Report results of multiple completion ar Recompletion Report an	a rol tourn	
13. Describe Prop give subs 1-27-95:	source or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol	Installation. I pertiment details, and give pertiment dates, including estimated date of al depths for all markers and zones pertiment to this work.)* e.	Co starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is directic	a rol tourn	
1]. Describe Prop give subs 1-27-95: 1-31-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375",	installation. I pertiment details, and give pertiment dates, including estimated date of al depths for all markers and zones pertiment to this work.)* e. 48#/ft., H-40, 8rd casing, set at	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
1]. Describe Prop give subs 1-27-95: 1-31-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375",	installation. I pertiment details, and give pertiment dates, including estimated date of al depths for all markers and zones pertiment to this work.)* e. 48#/ft., H-40, 8rd casing, set at	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel	installation. I pertiment details, and give pertiment dates, including estimated date of cal depths for all markets and zones pertiment to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8 $\#/gallon$).	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM	Installation. I pertinent details, and give pertinent dates, including estimated date of cal depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95:	word or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of	Installation. I pertiment details, and give pertiment dates, including estimated date of cal depths for all markers and zones pertiment to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CAU d, 14.8#/gallon). 2-1-95. cement to surface.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Naited on coment 8 ho	Installation. I pertinent details, and give pertinent dates, including estimated date of cal depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. cement to surface.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	Nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Naited on coment 8 ho	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B.	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95:	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, 0.K.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95: 2-02-95: 2-03-95	nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sace (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000 Drilling at 1440' K.F	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, O.K. 3.	co starting any pr t 400.1 CL2 and	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95: 2-02-95: 2-03-95: 2-03-95	bosed or Completed Operations (Clearly state at surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, O.K. 3.	starting any pr	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	maily drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95: 2-02-95: 2-03-95 14. 1 hereby cen	nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sace (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000 Drilling at 1440' K.F	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, O.K. 3.	co starting any pr t 400.1 CL2 and	ole: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	nally drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95: 2-02-95: 2-03-95 14. 1 hereby cet Signed	nosed or Completed Operations (Clearly state a surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000 Drilling at 1440' K.F	Installation. I pertinent details, and give pertinent dates, including estimated date of al depths for all markers and zones pertinent to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. sement to surface. burs. 0 psig with rig pump, O.K. 3.	co starting any pr t 400.1 CL2 and	ble: Report results of multiple compl mpletion or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s	nally drille	
13. Describe Prop give subs 1-27-95: 1-31-95: 2-01-95: 2-02-95: 2-03-95 14. 1 hereby cet Signed Conditions	nosed or Completed Operations (Clearly state at Surface locations and measured and true vertice Spudded Conductor hol Spudded 17-1/2" hole. Ran 9 joints 13.375", Ran 3 Howco centraliz Cemented with 400 sac (1.32 cu.ft./sk. yiel Plug down at 5:04 PM Circulated 57 sacks of Waited on cement 8 ho Tested Casing to 1000 Drilling at 1440' K.F	Installation. I pertiment details, and give pertiment dates, including estimated date of all depths for all markers and zones pertiment to this work.)* e. 48#/ft., H-40, 8rd casing, set at ers on joints Nos. 1, 3, and 5. ks Premium Plus cement with 2% CA d, 14.8#/gallon). 2-1-95. cement to surface. burs. 0 psig with rig pump, O.K. 3. AMA Tule Agent for Robert N. Enf	co starting any pr t 400.1 CL2 and ield	 bit: Report results of multiple complementation or Recompletion Report an opused work. If well is direction 3' K.B. 1/4# flocele/s 	sk., 1995	

*See Instruction on Reverse Side

ċ.