

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL AP/NO. 30-025-32783 32873
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1306
7. Lease Name or Unit Agreement Name: New Mexico "R" State NCT-1
8. Well No. 16
9. Pool name or Wildcat Vacuum Drinkard
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☒ Injection

2. Name of Operator
Chevron Texaco Corporation

3. Address of Operator
P.O. Box 3109 Midland, Texas 79702


4. Well Location
Unit Letter G : 1410 feet from the North line and 2630 feet from the East line
Section 6 Township 18S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>			

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2 CIBP @ 7575, spot 25 sxs. Plug 7575 to 7325 (Drinkard) Tag @ 7312
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
3. Spot 25 sxs plug 3800 to 3600 (Queen)
4. Spot 25 sxs. Plug 2800 to 2600 (Yates, B-Salt) Tqag @ 2528
5. Spot 50 sxs. Plug 1600 to 1200 (8 5/8 Shoe, T-Salt) Tag @ 1178
6. CIRC cmt. 30 to surf w/15 sxs. - Install dry hole marker (1/7/02)



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 1/7/02

Type or print name Jimmy BAGLEY Telephone No 915 683-4996
(This space for State use)

APPROVED BY Johnny Robinson TITLE COMPLIANCE OFFICER DATE 1/7/02
Conditions of approval, if any:

GW