## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, \* "nerals and Natural Resources Department

Form C-103

CONDITIONS OF AFFROVAL, IF ANY:

Form	C.	·Ια	5
Revis	ьd	1-1	-8

P.O. Box 1980, Hobbs, NM \$8240	OIL CONSERVATION		WELL API NO.
310 Old Santa Fe 17au, Room 206		30-025-32888	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	ii∞ 87503	5. Indicate Type of Lasse
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	)		STATE X FEE 6. State Oil & Gas Lease No.
SUNDRY NO	TICES AND REPORTS ON WE	IIS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lesse Name or Unit Agreement Name	
(FORM	C-101) FOR SUCH PROPOSALS.)	EPANII I	SMGSAU
I. Type of Well: OIL GAS WELL X WELL	OTHER		
2. Name of Operator			8. Well No.
CROSS TIMBERS OPERA	TING COMPANY		610 9. Pool name or Wildcat
P.O. Box 52070, Midland, Texas 79710-2070		MALJAMAR GRAYBURG SAN ANDRES	
4. Well Location		-	
Unit Letter M: 1,3	10 Feet From The South	Line and 75	60 Feet From The West Line
Section 29	Township 17S p		NIMPM LEA County
	4,051' GR, 4,	· · · · · · · · · · · · · · · · · · ·	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check	Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other Data
**************************************		SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
		COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DIVILLING	OFIG PENGANDARANDONMENT
TEMPORARILY ABANDON  PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CE	
	CHANGE PLANS	1	MENT JOB X
PULL ORALTER CASING  OTHER:  12. Describe Proposed or Completed Operator SEE RULE 1103.  Drill to TD @ 4,397'  Run 126 jts 5-1/2".  RU Halliburton & cem	w/ 7-7/8" bit. 15.50# & 17#, J55 & L80 ent w/700sx Premium Plu w/0.6% Hacao 322, 5#/s	CASING TEST AND CEI OTHER: MORT/WO and give pertinest dates, included  O, LTC used casing us w/3% Econolite	MENT JOB X  OCU X  uding estimated date of starting erry proposed  ag, set @ 4,397'.  e & 1/4#/sx Flocele. Tail in
OTHER:  12. Describe Proposed or Completed Operator's SEE RULE 1103.  Drill to TD @ 4,397' Run 126 jts 5-1/2".  RU Halliburton & cem w/200sx Premium Plus circulate cement.  Run temp survey, TOC MORT - WOCU.	w/ 7-7/8" bit. 15.50# & 17#, J55 & L80 ent w/700sx Premium Plu w/0.6% Hacao 322, 5#/s @ 300'.	CASING TEST AND CEI OTHER: MORT/WO and give periment dates, included,  O, LTC used casing us w/3% Econolite ex Microbond, and	MENT JOB X  OCU  Adding estimated date of starting any proposed  ag, set @ 4,397'.  e & 1/4#/sx Flocele. Tail in  1 1/4#/sx Versaset. Did not
OTHER:  12. Describe Proposed or Completed Operator's SEE RULE 1103.  Drill to TD @ 4,397' Run 126 jts 5-1/2".  RU Halliburton & cem w/200sx Premium Plus circulate cement.  Run temp survey, TOC MORT - WOCU.  Ibereby certify that the information shows in true signature  TYPEOR FRINT NAME George E.  (Thus space for State Use)  ORIGINAL S	entions (Clearly state all pertinent details.  w/ 7-7/8" bit.  15.50# & 17#, J55 & L80 ent w/700sx Premium Plu w/0.6% Hacao 322, 5#/s  @ 300'.  Ramsey Jr.  GIGNED BY JERRY SEXTON BICT I SUPERVISOR	casing test and cell other: MORT/WO and give periment date, included, the condition of the condition of the cell o	MENT JOB X  OCU X  Inding estimated date of starting eny proposed  ag, set @ 4,397'.  e & 1/4#/sx Flocele. Tail in  al 1/4#/sx Versaset. Did not  India 1/4#/sx Versaset.

المراب والمراب والمنافع منبوا والمراب والمراب والمنافعين والمنافع والمراب والمنافع والمنافع والمنافع والمنافع