UNITED STATES JUNE 1990) UNITED STATES JUNE 1990) UNITED STATES BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not, use this form for proposals to drill or to deepen or reentry to a different reservoir. SUBMIT	IL CUNS. COMMISSION Ox 1980
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. SUBMIT	. NEW MEXICO 88240
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. SUBMIT () SUBMIT	FORM APPROVED
SUMPRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. SUBMIT () Type of Well Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT () Type of Well Well Other SUMMIDLAND, TEXAS 79702 1. Name of Operator SOUTHWEST ROYALTIES, INC. 3. Address and Telephone No. P. O. BOX 11390, MIDLAND, TEXAS 79702 1. Location of Well (Focuses, Sec., T., R., M., or Survey Description) 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR ONE OF ACTION TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Injeti Subsequent Report Final Abandonment Notice Abandonment Abandonment Abandonment Plugging Back Other 108, tie back, perf & Other 108, tie ba	lget Bureau No. 1004-0135 Expires: March 31, 1993
SUMMY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Substitution Substitu	Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Submit Submi	4189
Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT	in, Allottee or Tribe Name
SUBMIT Substitution State Other Other State Other Other State Other Othe	· · · · · · · · · · · · · · · · · · ·
Name of Operator St. Well Other St. Well M.	or CA, Agreement Designation
SOUTHWEST ROYALTIES, INC. 3. Address and Telephone No. P. O. BOX 11390, MIDLAND, TEXAS 79702 4. Location of Well (Footage, Sec., T., R. M., or Survey Description) 330' FNL & 660' FEL SEC 34, T17S-R33E, LEA CO., NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OR TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF Hospital Abandonment Abandonment Recompletion Plugging Back Altering Casing Other log, tie back, perf & Distribute subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9-13-95 TIH ran GR/CBL 4897-2980', TOC @ 3106'. 9-14-95 RU Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 ful cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE.	me and No.
P. O. BOX 11390, MIDLAND, TEXAS 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330. FNL & 660 FEL SEC 34, T17S-R33E, LEA CO., NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OR OTHER SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Plugging Back Other 108, tie back, perf & Note active subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9-13-95 TIH ran GR/CBL 4897-2980', TOC @ 3106'. 9-14-95 Ru Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 ful cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE.	
330' FNL & 660' FEL SEC 34, T17S-R33E, LEA CO., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR CONTICE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Notice of Intent Subsequent Report Final Abandonment Notice Final Abandonment Notice Tinal Abandonment No	nd Peol or Exploratory Area
330. FNL & 660. FEL SEC 34, T17S-R33E, LEA CO., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR CONTICE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Injent Subsequent Report Final Abandonment Notice Tinal Abandonment Notice Altering Casing Repair Toket Jogs, tie back, perf & Discontinue date of starting any proposor give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Tinal Abandonment Notice New Your Location Notice Tinal Abandonment Notice Altering Casing Repoir Altering C	or Pagist, State W
TYPE OF SUBMISSION Notice of Intent Abandonment Charles Recompletion New Recompletion Recompletion New Recompletion Reco	COUNTY, NEE
Notice of Interit Abandonment Recompletion New New Recompletion New	THER DATA
Recompletion New New	 .
Subsequent Report Plugging Back Wat Casing Repair Casing Repair Casing Repair Casing Repair Complete Casing Repair Complete	nge of Plans
Casing Repair Attering Casing Other 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9-13-95 TIH ran GR/CBL 4897-2980', TOC @ 3106'. 9-14-95 RU Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 full cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE.	Construction -Routine Fracturing
Final Abandonment Notice Altering Casing Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back, perf & Dis Other log, tie back	er Shut-Off
Some Log, tie back, perf & Discribe Acidize Completed	version to Injection
Ompletic 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9-13-95 TIH ran GR/CBL 4897-2980', TOC @ 3106'. 9-14-95 RU Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 full cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	pose Water
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9-13-95 TIH ran GR/CBL 4897-2980', TOC @ 3106'. 9-14-95 RU Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 full cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	port results of multiple completion on Well n or Recompletion Report and Log form.)
9-14-95 RU Wedge WL ran csg inspection log from 4897-surface. 9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 ful cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	work. If well is directionally drilled,
9-15-95 Ran csg for tie back. TIH & BO csg @ 3032' WL. TOH w/69 ful cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	
cut off. 9-16-95 TIH w/71 jts screw into csg @ 3036. Perf 4801-4833' 2 JSPF w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	
w/4000 gals NEFE. 9-21-95 RU Wedge WL & TIH & perf 4725-4774' 29 shots, 2 runs. Acid NEFE. HOBBS INSPECTION OFFICE	l jts csg and one
NEFE. HOBBS INSPECTION OFFICE	, 34 holes. Acidize
9-23-95 Run pmp & rods. HOBBS INSPECTION OFFICE	ize w/3250 gals 15%
ACCEPTED FOR RECORD	
DATE 10-12-95 SIGNATURE UR'S	
14. I hereby certify that the foregoing is true and correct	
Signed McGratte Nelson Patton AREA SUPERVISOR Date	. 10-3-95
(This space for Federal or State office use)	
Approved by Title Date Conditions of approval, if any:	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

