Submit 3 copies to Appropriate
District Office

DISTRICT I

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503 P.O. Box 1980, Hobbs, NM 88240

WELL API NO.	
	l
30-025-33243	!
5. Indicate Type of Lease STATE X FEE	
6. State Oil & Gas Lease No. B-2148	
7. Lease Name or Unit Agreement Name	2/2/2/2/2
Caprock Maljamar Unit	
8. Well No. 243	
9. Pool name or Wildcat	
Maljamar Grayburg San Andres	
East	Line
County Lea	

		•					
O Box Drawer	DD, Artesia, NM	. 88210			5. Indicate Type S	of Lease TATE X FEE	
O. Bon Brawn					6. State Oil & G	as Lease No	
ISTRICT_III	n: \1.4 9	27410			o. State On & O	B-2148	,
000 Kio Brazos i	Rd., Aztec, NM 8						, , , , , , , , , , , , , , , , , , ,
	SUNDRY N	IOTICES AND REPORTS O	N WEI	LLS			
DO NOT US	E THIS FORM	I FOR PROPOSALS TO DRILL	OR TO I	DEEPEN OR PLUG BACK TO A			
	DIFFERENT !	RESERVOIR USE "APPLICATI	ON FOR	PERMII"	7. Lease Name	or Unit Agreement Name	
		01)FOR SUCH PROPOSALS.)			Caprock Ma	aljamar Unit	
Oil X	: Gas				•	•	
Well	Wel				0 77 11 27		
2. Name of Ope					8. Well No.	243	
		e Wiser Oil Company			9. Pool name or		
3. Address of O	perator 011	5 Preston Road, Suite 400, Dalla	s TX 7	5225		Gravburg San Andres	;
4. Well Locatio		3 Teston Road, Barte 400, Bart	10, 111				
	_	: 1384 Feet From The Sout	1	Line and 2453 Feet From	The East		Line
,	Unit Letter	1 1304 100 110 110 502				_	
	Section 28	Township 17S		33E NMPM	1. 1988 1988	County	Lea
		10. Elevation (Show		F, RKB, GR, etc.)			
		4172' (Ltura SNI-tina Deport or Otho	r Doto		<u> X.::</u>
11.			dicate N	lature of Notice, Report, or Other			
N	OTICE OF I	NTENTION TO:		SUBSEQUENT RE	PORT OF:		
ERFORM RE	MEDIAL WOR	K PLUG AND ABANDO	1	REMEDIAL WORK	ALTE	RING CASING	
EMPORARIL	Y ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	PLUG	AND ABANDONME	NT
	TER CASING			CASING TEST AND CEMENT JO	ов 🗌		
THER:			_ 🗆	OTHER: Perf & acidize			x
12 Descibe Pr	oposed or Comple	eted Operation (Clearly state all pertine	nt details, a	and give pertinent dates, including estimate	ed date of starting any	proposed work)	
SEE RUL		·					
	01/29/96	Perforate 4750, 51, 52, 53, 54,	55 (6 ho	les).			
	01/30/96	Set pkr @ 4680'. Acidize perf	s w/ 2000	gals 15% NEFE acid.			
	02/20/96	Set CIPB @ 4740'. Perforate	666, 70,	71, 72, 77, 78, 82, 83, 84, 87, 90,	91, 92, 95 (14 hole	es).	
	02/21/96	Acidize w/ 3000 gals 15% NE	FE acid.				
	02/23/96	Set RBP @ 4660'. Perforate 4 (24 holes). Acidize perfs 4615	615, 16, 5'-4654' w	17, 18, 19, 21, 23, 27, 28, 29, 30, 4/ 4000 gals 15% NEFE acid.	36, 41, 42, 43, 44,	45, 48, 49, 50, 51, 5	2, 53, 54
	02/26/96	Run 2-7/8" tbg. Set pkr @ 45	08'.				
I hereby certify the	at the information ab	pove is true an complete to the best of my kno	wledge and l	belief.	unit :		
SIGNATURE	Bū	the Esil	TITLE	Production Administrator		DATE06/19/	96
TYPE OR PRINT N	NAME BO	etty Epie			TELEPHONE NO.	(214)265-0080	
						HIL	904
(THIS SPACE FOR	CSTATE USE)	ORIGINAL SIGNE				ากม	26 1
A BOB CLEED BY		GARY WINK		Ε		DATE	
APPROVED BY _		- FIELD REP.	H				