Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATIO P.O. Box 208		WELL API NO. 30-025-33388
DISTRICT II P.O. Drawer DD, Ariesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		5. Indicate Type of Lesse STATE FEE
		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: Oil. GAS WELL X WELL OTHER		Pawnee APW State
2. Name of Operator YATES PETROLEUM CORPORATION		8. Well No.
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Pool name or Wildcat Wilcock Mid Vacuum Delaware Groundury
4. Well Location		
Unit Letter 11. 190 Per Floor III. 25 Per 35 F. Niver I.e.a. County		
Section 20 Township 105 Range (Manual Control of the Control of th		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ADMINISTRATION OF THE STATE OF T		
PULL OR ALTER CASING CASING TEST AND CEMENT JOB		الساء
OTHER:	OTHER TETTOTICS	
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-24-97 - Moved in and rigged up pulling unit. Unseat pump. TOOH with rods. Released tubing anchor and nippled up BOP. TOOH with 171 joints of tubing. Rigged up wireline. TIH with 4" casing guns and perforated 4738-4742' w/20 .42" holes (4 SPF - Grayburg). TOOH with casing guns and rigged down wireline. TIH with packer and RBP. Set RBP at 4832'. Loaded hole. Tested RBP to 2000 psi. Spotted 1-1/2 bbls acid at 4740'. Set packer at 4676'. Pressured annulus to 500#. Break down perforations. Acidized perfs. 4738-4742' w/1000 gallons 10% iron control HCL acid and ball sealers. Swabbed. Prep to move to Queen.		
TYPE OR PRINT NAME Rusty Klein	ibdid. Operations T	<u>телетноме но. 505/748-1</u> 471
(This space for State Use)		14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1