

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Amended Report

WELL API NO.	30-025-33428
5. Indicate Type of Lease	STATE ☒ FEE
6. State Oil / Gas Lease No.	B-1306
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	132
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101)" FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1870</u> Feet From The <u>NORTH</u> Line and <u>890</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	CORRECT WTR FLOW, STIMULATE GLORIETA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-25-00: MIRU. NDWH, NUBOP. REL TAC. TIH W/BIT & CSG SCRAPER. PU TBG. STOP BIT @ 1525'.
 7-26-00: TIH W/RBP & PKR. SET RBP @ 6063'. PULL PKR TO 6044'. TEST RBP & CSG TO 500 PSI-OK. SPOT 2 SX SAND ON RBP.
 7-27-00: TIH W/PERF GUN & PERF @ 1990'.
 7-28-00: REL PKR. TIH W/CMT RET. TBG. PUMP THRU RET. SET RET @ 1847'. TEST TBG TO 2000-OK. MIX 200 SX CL C CMT & 200 SX C NEAT.
 7-31-00: TIH W/BIT & DC'S TO 1843'. DRILL 4' CMT. TAG CMT RET @ 1847'. DRILL RET 176' CMT TO 2025.
 8-01-00: TIH W/LOG TOOL. RAN CBL LOG FR RBP @ 6053-1500'. TIH W/PKR, SN & TBG. SET PKR @ 1453'. PERF CSG @ 1550'. PUMP THRU PERFS.
 8-02-00: REL PKR. TIH W/RET, & TBG TO 1450.
 8-03-00: SET RET @ 1450. MIX 200 SX C 35/65 & 145 SX CL C.
 8-04-00: TIH W/BIT & TBG TAG @ 1444. DRILL 6' CMT TAG RET @ 1450. DRILL RET. HARD CMT TO 1610.
 8-07-00: TIH W/BIT, CSG SCRAPER TO 2512'. TIH W/PKR & TBG TO 1453. REL PKR. LOWER & SET @ 1673. REL PKR. TIH W/TBG TO 1603'.
 8-08-00: SPOT SQUEEZECRETE 1610-1308.
 8-10-00: TAG @ 1403'. DRILL 1403-1600. TEST/CHART CSG TO 540 PSI. TIH TO 6039. DISPL W/2% KCL.
 8-11-00: TIH W/LOG TOOL. CORR W/OPEN HOLE LOG. LOG 6032-5790. PERF 5982-5990, 5998-6010, 6018-26. TIH W/PKR, SN & TBG TO 5889'. SET PKR.
 8-14-00: ACIDIZE GLORIETA PERFS 5982-6026 W/6000 GALS 15% NEFE ACID. RU SWAB. FL @ SURF. END FL @ 5600'.
 8-15-00: REL PKR. TIH W/RETR TOOL. WASH SAND OFF RBP @ 6063'. REL RBP.
 8-16-00: TIH W/WS. TIH W/CIBP & SET @ 5930. TOP PERF @ 5982. PULL TBG TO 5900. TEST TO 500 PSI-OK. TIH W/RDS.
 8-17-00: DISPL W/130 BBLs TRTD WTR. TEST FR CIBP @ 5930 TO SURF. CHART FOR NMOC. NDBOP. NUWH. CLN LOCATION. RIG DOWN.
 8-25-00: WELL IS SHUT IN-OIL. UNSUCCESSFUL WORKOVER. FINAL REPORT

This Approval of Temporary Abandonment Expires 8-25-2005

****WELL IS NOW TEMPORARILY ABANDONED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 8/25/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

BY CONDITIONS OF APPROVAL, IF ANY TITLE

DATE