

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33428
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1306
7. Lease Name or Unit Agreement Name	NEW MEXICO R STATE NCT-1
8. Well No.	18
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter H : 1870 Feet From The NORTH Line and 890 Feet From The EAST Line
Section 6 Township 18-S Range 35-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA LOWER PADDOCK, PERF UPPER PADDOCK ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-08-99: MIRU. TRY TO UNSET PUMP-STUCK. JAR ON PUMP-NO LUCK. BACK OFF RDS ON TOP OF PUMP. TOH W/LINER, RODS, SNKR BARS. NDWH. NUBOP.
1-11-99: SWAB DN 2 7/8" TBG. TOH W/TBG, SN, PERF SUB, OPSMA. TIH W/CIBP & SET @ 6250'. LOAD & TEST CSG & PLUG TO 500#. TIH W/PERF GUN. PERF CSG IN PADDOCK FORMATION FR 6087-6093, 6095-6109' W/2 JSPF @ 120 DEG PHAZING. TIH W/BAILER & DUMP 35' CMT ON TOP OF CIBP FOR NEW PBTD OF 6215'.
1-12-99: TIH W/PKR, SN, & TBG. TEST TBG TO 5000 PSI. PSA 6027'. PSI CSG TO 500 PSI-OK. ACIDIZE PERFS @ 6087-6109' W/2000 GALS 15% NEFE ACID. SWAB FL @ SURF. END FL @ 5300'.
1-13-99: FL @ 4000'. END FL @ 5700'. REL PKR. TOH W/100 JTS TO 2948'.
1-14-99: TOH W/PKR. TIH W/OPMA, PERF SUB, SN, IPC SUBS, TBG, TAC. SET @ 18' KB. OPMA @ 6200'. SN @ 6165'. TAC @ 5808'. NDBOP. SET TAC. NUW. TIH W/GAS ANCHOR, PUMP, LIFT SUB, K-BARS, RODS. HANG WELL ON. LOAD & TEST OK.
2-01-99: ON 24 HR OPT. PUMPED 13 BO, 11 BW, & 2 MCF. GOR-154. API GRAV-38.6@60. PERFS: 6087-6109'. (UPPER PADDOCK)
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 2/1/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JC